



Aviation Investigation Final Report

Location:	MANITO, Illinois	Accident Number:	CHI97LA185
Date & Time:	June 27, 1997, 09:50 Local	Registration:	N7015N
Aircraft:	Pzl-Mielec M-18A	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 137: Agricultural		

Analysis

The pilot reported that he departed runway 22 using 40 inches of manifold pressure. During takeoff climb, the engine lost power. As the pilot attempted to dump the chemical load, the engine regained full power. The pilot reported that the airplane was too low, and it impacted a powerline, then impacted the ground. The airplane bounced back into the air. The pilot reported that he flew back to land, and received confirmation that the landing gear were operable before he landed. He flew for about a total of five minutes before making an uneventful landing. Witnesses reported that the engine sounded fine as the airplane was taxiied back to the hangar. The engine was inspected, and no anomaly was found.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: loss of engine power for undetermined reason(s).

Findings

Occurrence #1: LOSS OF ENGINE POWER
Phase of Operation: TAKEOFF

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

2. OBJECT - WIRE, TRANSMISSION

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: OTHER

Factual Information

On June 27, 1997, at 0950, central daylight time, a Pzl Mielec, M-18A, N7015N, operated by Mitchell Flying Service, sustained substantial damage during takeoff when it experienced a loss of power, hit a powerline, and impacted a field. The aircraft was able to become airborne again and returned to land at Manito Mitchell Airport, Manito, Illinois. The 14 CFR Part 137 crop duster had departed the airport on a local aerial application flight. The commercial pilot was not injured. Visual meteorological conditions prevailed and no flight plan was filed.

The pilot reported that he departed runway 22 using 40 inches of manifold pressure. During takeoff climb the engine lost power. As the pilot was attempting to dump the chemical load the engine regained power. The pilot reported that the airplane was too low and it impacted a powerline and then impacted the ground. The impact separated the chemical sprayer from the airplane which dumped the chemical load. The airplane bounced back into the air. The pilot reported that he flew back to land but received confirmation that the landing gear were operable before he landed. He flew for about a total of five minutes before making an uneventful landing. Witnesses reported that the engine sounded fine when it taxiied back to the hangar.

The engine was inspected by an Airworthiness Inspector from the Federal Aviation Administration and no anomalies were found.

Pilot Information

Certificate:	Commercial	Age:	64, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--w/ waivers/lim	Last FAA Medical Exam:	January 3, 1997
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	9500 hours (Total, all aircraft), 350 hours (Total, this make and model), 9350 hours (Pilot In Command, all aircraft), 75 hours (Last 90 days, all aircraft), 40 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Pzl-Mielec	Registration:	N7015N
Model/Series:	M-18A M-18A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	120-18
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	October 2, 1996 Annual	Certified Max Gross Wt.:	9260 lbs
Time Since Last Inspection:	49 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	WSK
ELT:	Not installed	Engine Model/Series:	ASZ-621R-16
Registered Owner:	MITCHELL FLYING SERVICE	Rated Power:	954 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PIA ,660 ft msl	Distance from Accident Site:	25 Nautical Miles
Observation Time:	08:54 Local	Direction from Accident Site:	10°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	170°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	24°C / 17°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(C45)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	09:45 Local	Type of Airspace:	Class G

Airport Information

Airport:	MANITO MITCHELL C45	Runway Surface Type:	Asphalt
Airport Elevation:	500 ft msl	Runway Surface Condition:	Dry
Runway Used:	22	IFR Approach:	
Runway Length/Width:	3000 ft / 100 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	40.420604,-89.779571(est)

Administrative Information

Investigator In Charge (IIC):	Silliman, Jim
Additional Participating Persons:	SCOTT BURKE; SPRINGFIELD , IL
Original Publish Date:	May 21, 1998
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=10612

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).