



Aviation Investigation Final Report

Location: Hood River, Oregon **Accident Number:** WPR22LA370

Date & Time: September 3, 2022, 15:00 Local Registration: N278SE

Aircraft: ALISPORT SRL SILENT 2 ELECTRO Aircraft Damage: Substantial

Defining Event: Hard landing **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the powered glider reported that, after takeoff he realized that both the left wing and tail dolly were still attached. The pilot returned to the airport and prepared for a straight in landing to the grass runway with the electric propellor off and the main wheel retracted. The fuselage was substantially damaged when the glider landed hard. The pilot reported that there were no preaccident mechanical failures or malfunctions with the glider that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper landing flare which resulted in a hard landing. Contributing to the accident was the pilot's failure to follow the checklist to remove the wing wheel and tail dolly before takeoff.

Findings

Aircraft Landing flare - Not attained/maintained

Personnel issues Use of checklist - Pilot

Factual Information

History of Flight

|--|

Pilot Information

| Certificate: | Private | Age: | 68,Male |
|---------------------------|---|-----------------------------------|--------------------|
| Airplane Rating(s): | Single-engine land; Single-engine sea | Seat Occupied: | Single |
| Other Aircraft Rating(s): | Glider | Restraint Used: | 4-point |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | |
| Medical Certification: | Class 3 With waivers/limitations | Last FAA Medical Exam: | September 29, 2021 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | October 15, 2021 |
| Flight Time: | 2199 hours (Total, all aircraft), 116 hours (Total, this make and model), 2075 hours (Pilot In Command, all aircraft), 55 hours (Last 90 days, all aircraft), 37 hours (Last 30 days, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | ALISPORT SRL | Registration: | N278SE |
|-------------------------------|----------------------------|-----------------------------------|---------------|
| Model/Series: | SILENT 2 ELECTRO | Aircraft Category: | Glider |
| Year of Manufacture: | 2016 | Amateur Built: | |
| Airworthiness Certificate: | Experimental (Special) | Serial Number: | 2078 |
| Landing Gear Type: | Retractable - Tailwheel | Seats: | 1 |
| Date/Type of Last Inspection: | Condition | Certified Max Gross Wt.: | 694 lbs |
| Time Since Last Inspection: | | Engines: | 1 Electric |
| Airframe Total Time: | 16 Hrs at time of accident | Engine Manufacturer: | AMA/EXPRL7 |
| ELT: | | Engine Model/Series: | LZ Designs |
| Registered Owner: | On file | Rated Power: | 35 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |
| | | | |

Page 2 of 4 WPR22LA370

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|------------------------------|--------------------------------------|-------------------|
| Observation Facility, Elevation: | K42S,630 ft msl | Distance from Accident Site: | 16 Nautical Miles |
| Observation Time: | 14:53 Local | Direction from Accident Site: | 102° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 4 knots / | Turbulence Type Forecast/Actual: | None / |
| Wind Direction: | 290° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30.04 inches Hg | Temperature/Dew Point: | 23°C / 11°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ation | |
| Departure Point: | Hood River, OR | Type of Flight Plan Filed: | None |
| Destination: | Hood River, OR | Type of Clearance: | None |
| Departure Time: | | Type of Airspace: | Class G |

Airport Information

| Airport: | KEN JERNSTEDT AIRFIELD 4S2 | Runway Surface Type: | Grass/turf |
|----------------------|----------------------------|----------------------------------|--------------------------------------|
| Airport Elevation: | 638 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 25 | IFR Approach: | None |
| Runway Length/Width: | 2000 ft / 100 ft | VFR Approach/Landing: | Precautionary landing;Straight-in |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 45.672777,-121.53386(est) |

Page 3 of 4 WPR22LA370

Administrative Information

Investigator In Charge (IIC):

Additional Participating Persons:

Original Publish Date:

January 9, 2023

Last Revision Date:

Investigation Class:

Class 4

Note:

The NTSB did not travel to the scene of this accident.

Investigation Docket:

https://data.ntsb.gov/Docket?ProjectID=106143

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 WPR22LA370