

# **Aviation Investigation Final Report**

**Location**: New York, New York **Accident Number**: DCA23LA114

Date & Time: January 2, 2023, 16:35 Local Registration: N928XJ (A1); EI-EJM

(A2)

Aircraft:

BOMBARDIER INC CL-600-2D24
(A1); Airbus A330 (A2)

Aircraft Damage:

Substantial (A1);
Minor (A2)

80 None (A1); 259

Ground collision Injuries: None (A2)

Flight Conducted Under: Part 121: Air carrier - Scheduled (A1); Part 129: Foreign (A2)

#### **Analysis**

**Defining Event:** 

ITA Airways flight 610, an Airbus A330-202, EI-EJM, collided with Endeavor Air flight 4994 (d.b.a. Delta Air Lines), a Bombardier CRJ-900LR, N928XJ, while taxiing after landing at John F. Kennedy International Airport (JFK), Queens, New York. There were no injuries to the passengers and crew onboard either airplane, and the Endeavor Air airplane received substantial damage. Endeavor Air flight 4994 was operating under 14 *Code of Federal Regulations* Part 121 as a regularly scheduled passenger flight, and ITA Airways flight 610 was operating under 14 *Code of Federal Regulations* Part 129 as a scheduled international passenger flight.

#### **Endeavor Air flight 4994**

Endeavor Air flight 4994 landed on runway 22L at JFK and proceeded on taxiway juliet, then to taxiway alpha, and then initiated a turn onto taxiway KF into the ramp area. The Endeavor Air flight crew reported being cleared to enter the Terminal 4 ramp and taxi to gate B44. Ramp control advised the flight crew to give way to traffic parking at gate B42 before parking at their assigned gate. The Endeavor Air flight crew moved forward onto taxiway KF, and the flight crew stated they pulled as far forward as they could into the ramp area but could not pull any further forward due to an airplane awaiting to park at another gate. The flight crew remained stationary and continued to monitor ground and ramp frequencies while waiting to park at their assigned gate.

#### ITA Airways flight 610

ITA Airways flight 610 landed on runway 22L and taxied to the ramp area using taxiway alpha. The flight crew reported they saw the Endeavor Air airplane turning onto taxiway KF and recalled the Endeavor Air airplane stopping as soon as it entered the taxiway. As ITA Airways proceeded on taxiway alpha, the captain, who was the pilot monitoring, noticed the tail of the Endeavor Air airplane was close to taxiway alpha and reduced ground speed. The ITA Airways flight crew stated they presumed they were clear of the Endeavor Air airplane since their airplane was taxiing on the centerline of taxiway alpha.

The Endeavor Air flight crew reported feeling a severe shaking which prompted them to look out of the left side of the airplane where they observed that the ITA Airways airplane was missing its right winglet. This prompted the Endeavor Air flight crew to conclude their airplane may have been struck by ITA Airways airplane and they instructed air traffic control (ATC) that their airplane needed to remain stationary until the damages were confirmed and an exterior check could be performed.

ITA Airways flight 610 proceeded to their gate. Post accident inspection revealed substantial damage to the right elevator and horizontal stabilizer structure of Endeavor Air's airplane, and minor damage to the right winglet of ITA Airways' airplane.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

ITA Airways flight crew's incorrect evaluation of the clearance between their airplane and another airplane stopped on an adjoining taxiway.

#### **Findings**

Environmental issues (A1)	Positioning/available space - Compliance w/ procedure
Environmental issues (A2)	Dark - Awareness of condition
Personnel issues (A2)	Decision making/judgment - Flight crew

Page 2 of 8 DCA23LA114

## **Factual Information**

## History of Flight

Taxi-from runway (A1)	Ground collision (Defining event)
Taxi-from runway (A2)	Ground collision

### Pilot Information (A1)

Certificate:	Airline transport; Commercial; Flight instructor	Age:	30,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	June 30, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	October 5, 2022
Flight Time:	3391 hours (Total, all aircraft), 1302 hours (Total, this make and model), 2140 hours (Pilot In Command, all aircraft), 110 hours (Last 90 days, all aircraft), 27 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

## **Co-pilot Information (A1)**

Certificate:	Airline transport; Commercial; Military	Age:	31,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	5-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	September 20, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	October 15, 2022
Flight Time:		nours (Total, this make and model), 17 ast 90 days, all aircraft), 67 hours (Las	

Page 3 of 8 DCA23LA114

#### **Pilot Information (A2)**

Certificate:	Airline transport	Age:	62,Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	July 23, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	January 21, 2022
Flight Time:	20400 hours (Total, all aircraft), 8500 hours (Total, this make and model), 14900 hours (Pilot In Command, all aircraft), 230 hours (Last 90 days, all aircraft), 28 hours (Last 30 days, all aircraft), 9 hours (Last 24 hours, all aircraft)		

## **Co-pilot Information (A2)**

Certificate:	Airline transport	Age:	44,Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	August 2, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	November 29, 2022
Flight Time:	8700 hours (Total, all aircraft), 66 hours (Total, this make and model), 105 hours (Last 90 days, all aircraft), 45 hours (Last 30 days, all aircraft), 9 hours (Last 24 hours, all aircraft)		

## Other flight crew Information (A2)

Certificate:	Airline transport	Age:	
Airplane Rating(s):		Seat Occupied:	Center
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):		Second Pilot Present:	Yes
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	13480 hours (Total, all aircraft)		

Page 4 of 8 DCA23LA114

## Aircraft and Owner/Operator Information (A1)

Aircraft Make:	BOMBARDIER INC	Registration:	N928XJ
Model/Series:	CL-600-2D24 CRJ-900LR	Aircraft Category:	Airplane
Year of Manufacture:	2008	Amateur Built:	
Airworthiness Certificate:	Transport	Serial Number:	15190
Landing Gear Type:	Retractable - Tricycle	Seats:	95
Date/Type of Last Inspection:	January 2, 2023 Continuous airworthiness	Certified Max Gross Wt.:	84500 lbs
Time Since Last Inspection:		Engines:	2 Turbo fan
Airframe Total Time:	33167 Hrs at time of accident	Engine Manufacturer:	GE
ELT:	C126 installed, not activated	Engine Model/Series:	CF34-8C5
Registered Owner:	DELTA AIR LINES INC	Rated Power:	14510 Lbs thrust
Operator:	Endeavor Airlines	Operating Certificate(s) Held:	Flag carrier (121)
Operator Does Business As:	Delta Connection	Operator Designator Code:	REXA

## Aircraft and Owner/Operator Information (A2)

Aircraft Make:	Airbus	Registration:	EI-EJM
Model/Series:	A330 202	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	1308
Landing Gear Type:	Retractable - Tricycle	Seats:	271
Date/Type of Last Inspection:	Continuous airworthiness	Certified Max Gross Wt.:	507063 lbs
Time Since Last Inspection:		Engines:	2 Turbo fan
Airframe Total Time:	40423 Hrs at time of accident	Engine Manufacturer:	general electric
ELT:	Installed, not activated	Engine Model/Series:	CF6-80E
Registered Owner:	MDCA 10 Ltd	Rated Power:	
Operator:	Italia Trasporto Aereo Spa	Operating Certificate(s) Held:	Foreign air carrier (129)
Operator Does Business As:	ITA Airways	Operator Designator Code:	

Page 5 of 8 DCA23LA114

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night
Observation Facility, Elevation:	KJFK	Distance from Accident Site:	
Observation Time:	17:51 Local	Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>		Visibility	10 miles
Lowest Ceiling:	Broken / 3700 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.14 inches Hg	Temperature/Dew Point:	9°C / 7°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Romulus, MI (KDTW) (A1); Fiumicino, Italy (LIRF) (A2)	Type of Flight Plan Filed:	IFR (A1); IFR (A2)
Destination:	New York, NY (A1); New York, NY (KJFK) (A2)	Type of Clearance:	IFR (A1); IFR (A2)
Departure Time:	16:35 Local (A1)	Type of Airspace:	Class B (A1)

### **Airport Information**

Airport:	John F. Kennedy International	Runway Surface Type:	Asphalt
	Airport KJFK		•
Airport Elevation:	13 ft msl	<b>Runway Surface Condition:</b>	
Runway Used:	22L	IFR Approach:	Unknown
Runway Length/Width:	8400 ft / 200 ft	VFR Approach/Landing:	

## Wreckage and Impact Information (A1)

Crew Injuries:	4 None	Aircraft Damage:	Substantial
Passenger Injuries:	76 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	80 None	Latitude, Longitude:	40.635494,-73.782786(est)

Page 6 of 8 DCA23LA114

## Wreckage and Impact Information (A2)

Crew Injuries:	11 None	Aircraft Damage:	Minor
Passenger Injuries:	248 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	259 None	Latitude, Longitude:	40.635494,-73.782786(est)

Page 7 of 8 DCA23LA114

#### **Administrative Information**

Investigator In Charge (IIC):	Bower, Daniel
Additional Participating Persons:	FAA; FAA
Original Publish Date:	July 17, 2024
Last Revision Date:	
Investigation Class:	Class 4
Note: The NTSB did not travel to the scene of this accident.	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106534

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 8 of 8 DCA23LA114