



Aviation Investigation Final Report

Location:	Auburn, Nebraska	Accident Number:	CEN23FA077
Date & Time:	January 11, 2023, 19:24 Local	Registration:	N22859
Aircraft:	Cessna 150H	Aircraft Damage:	Substantial
Defining Event:	Loss of control in flight	Injuries:	2 Fatal
Flight Conducted Under:	Part 91: General aviation - Instructional		

Analysis

The flight instructor and student pilot flew a visual arrival to a non-towered airport in dark night visual meteorological conditions. Flight track information revealed that the airplane approached the airport and its last recorded position was consistent with a left downwind entry to the traffic pattern. The wreckage was located about 1.2 miles south of the runway, where the airplane impacted a farm field in a near wings-level and moderate nose-down attitude.

Examination of the airplane and engine revealed no evidence of a mechanical failure or malfunction that would have precluded normal operation. The carburetor heat control was in the full forward (off) position at the accident site and the wing flaps were retracted. The weather conditions around the time of the accident were conducive to the development of serious carburetor icing at cruise power settings. The propeller spinner and both propeller blades exhibited minimal rotational damage, and the airplane's impact attitude was consistent with a loss of control.

The cockpit was equipped with flood 'strip' lights, which the flight instructor had previously reported could make viewing the in-set instruments in the cockpit more difficult at night.

It is likely that the pilots were maneuvering to land before the accident occurred and would have been operating the airplane at a reduced engine power setting. The reduced power, lack of carburetor heat, and the atmospheric conditions present at the time would have significantly increased the engine's susceptibility to the development of carburetor icing, and resulted in a loss of engine power. Given the lack of flight track information, and witnesses, whether the accident occurred during the approach for the first landing or during a subsequent traffic pattern/landing could not be determined. The extent to which the dark night conditions,

airplane interior lighting, and lack of cultural lighting in the vicinity of the airport may have contributed to the outcome also could not be determined.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The flight instructor's failure to maintain control after a loss of engine power due to carburetor icing while maneuvering for forced landing in dark night visual meteorological conditions.

Findings

Personnel issues	Aircraft control - Instructor/check pilot
Aircraft	(general) - Not used/operated
Environmental issues	Conducive to carburetor icing - Contributed to outcome
Environmental issues	Dark - Contributed to outcome

Factual Information

History of Flight

Approach	Fuel related
Approach	Loss of control in flight (Defining event)

On January 11, 2023, about 1924 central standard time, a Cessna 150H, N22859, was substantially damaged when it was involved in an accident near Farington Field Airport (K01), Auburn, Nebraska. The flight instructor and student pilot were fatally injured. The airplane was operated as a Title 14 Code of Federal Regulations Part 91 instructional flight.

According to automatic dependent surveillance-broadcast (ADS-B) information, the airplane departed Lincoln Airport (LNK), Lincoln, Nebraska, about 1845 and climbed to 3,500 ft mean sea level (msl). About 6 miles northwest of K01, the airplane began a descent and the last ADS-B information captured at 19:22:26 showed the airplane about 1.1 miles west of K01 at 105 knots groundspeed and about 1,900 ft msl (see Figure 1).




Figure 1. Airplane's Flight Track, K01 Airport, and Accident Site

The airplane impacted a field without crops while on a southeasterly heading, about 1.2 miles south of the runway 34 threshold at K01.

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	24, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	Yes
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	January 31, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	November 22, 2022
Flight Time:	(Estimated) 572 hours (Total, all aircraft), 15 hours (Total, this make and model), 107 hours (Last 90 days, all aircraft), 30 hours (Last 30 days, all aircraft)		

Student pilot Information

Certificate:	Student	Age:	41, Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	May 3, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	70 hours (Total, all aircraft), 20 hours (Total, this make and model)		

The flight instructor was issued his initial Federal Aviation Administration (FAA) flight instructor certificate on August 6, 2022, and a flight instructor instrument airplane rating on November 22, 2022. The flight instructor had accumulated about 36 total flight hours at night, and about 12 flight hours instructing students at night.

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N22859
Model/Series:	150H	Aircraft Category:	Airplane
Year of Manufacture:	1968	Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	15068568
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	June 1, 2022 Annual	Certified Max Gross Wt.:	1600 lbs
Time Since Last Inspection:	3298 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3272 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C91 installed, not activated	Engine Model/Series:	O-200A
Registered Owner:	On file	Rated Power:	100 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

The cockpit was equipped with flood 'strip' lights, which the flight instructor had previously reported could make viewing the in-set instruments in the cockpit more difficult at night (see Figure 2).



Figure 2. Accident Airplane Cockpit Illuminated by Flood Lights

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night
Observation Facility, Elevation:	KAFK, 1153 ft msl	Distance from Accident Site:	14 Nautical Miles
Observation Time:	19:15 Local	Direction from Accident Site:	345°
Lowest Cloud Condition:	Scattered / 12000 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	12 knots / None	Turbulence Type Forecast/Actual:	Unknown / Unknown
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	Unknown / Unknown
Altimeter Setting:	29.9 inches Hg	Temperature/Dew Point:	0°C / -2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Lincoln, NE (LNK)	Type of Flight Plan Filed:	None
Destination:	Lincoln, NE (LNK)	Type of Clearance:	None
Departure Time:	18:45 Local	Type of Airspace:	Class G

On the evening of the accident, United States Naval Observatory data indicated sunset occurred at 1717, the end of civil twilight was at 1747, and moonrise was at 2153 (after the accident). The accident site was surrounded by farm fields with an absence of cultural lighting.

According to the FAA Special Airworthiness Information Bulletin CE-09-35, Carburetor Icing Prevention, the probability of carburetor icing during the weather conditions of the accident was serious at cruise power.

Airport Information

Airport:	Farington Field K01	Runway Surface Type:	Concrete
Airport Elevation:	924 ft msl	Runway Surface Condition:	Dry
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	3750 ft / 60 ft	VFR Approach/Landing:	Traffic pattern

K01 was equipped with minimum intensity runway lighting for runway 16/34.

Wreckage and Impact Information

Crew Injuries:	2 Fatal	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 Fatal	Latitude, Longitude:	40.36171,-95.779759(est)

The airplane impacted a field without crops while on a southeasterly heading, about 1.2 miles south of the runway 34 threshold at K01. Ground impressions of the landing gear and crushing of the front fuselage (nose area) were consistent with a near wings level and moderate nose down attitude during impact.

All components of the airplane were observed at the impact site. Flight control continuity was confirmed. The wing flaps and wing flap actuator were both observed in the retracted position. Fuel drained from both wing tanks and the fuel bowl contained no indications of water or sediment.

The propeller spinner was crushed aft, with minimal rotational damage. Both propeller blades were bent aft, with minimal rotational scoring or polishing. The throttle control was observed in a mid-position and was bent, and the mixture control was near the full forward (rich) position. The carburetor heat control was observed in the full forward (off) position.

No evidence of pre-impact mechanical malfunctions were observed during examinations of the engine and airframe that would have precluded normal operation.

Medical and Pathological Information

An autopsy was performed on the flight instructor and student pilot by a medical examiner, as directed by the Nemaha County Coroner, Auburn, Nebraska. The cause of death was multiple blunt force injuries.

Toxicology testing of the flight instructor and student pilot performed by the FAA Forensic Sciences Laboratory did not identify any tested-for substances.

Administrative Information

Investigator In Charge (IIC): Folkerts, Michael

Additional Participating Persons: Nicholas Weiss; FAA, Flight Standards District Office; Lincoln, NE
Andrew Hall; Textron Aviation; Wichita, KS

Original Publish Date: September 5, 2024

Last Revision Date:

Investigation Class: [Class 3](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=106566>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).