



Aviation Investigation Final Report

Location: Soldotna, Alaska Accident Number: ANC23LA020

Date & Time: February 8, 2023, 17:00 Local Registration: N5987H

Aircraft: Piper PA-16 Aircraft Damage: Substantial

Defining Event: Loss of engine power (total) **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that on departure the engine lost then regained power. The pilot turned the airplane back toward the airport to land and, during the turn, a total loss of engine power occurred. The airplane impacted a snowbank during the landing. The airplane sustained substantial damage to the fuselage.

Postaccident examination of the engine revealed no evidence of any preimpact mechanical malfunctions or failures that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power for undetermined reasons.

Findings

Aircraft (general) - Failure

Not determined (general) - Unknown/Not determined

Factual Information

History of Flight

Takeoff	Loss of engine power (total) (Defining event)

On February 08, 2023, about 1700 Alaska daylight time, a Piper PA-16 airplane, N5987H sustained substantial damage when it was involved in an accident in Soldotna, Alaska. The pilot was not injured. The airplane was operated by the pilot as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

Shortly after takeoff, the engine lost partial power then regained power. The pilot turned the airplane back to the airport to perform an emergency landing. While in the turn, a total loss of engine power occurred and upon landing on airport property, the airplane impacted a snowbank. The airplane sustained substantial damage to the fuselage.

A postaccident examination of the engine, with oversight by a Federal Aviation Administration inspector, revealed no evidence of any preimpact mechanical malfunctions or anomalies that would have precluded normal operation.

The carburetor icing chart shows the weather conditions were conducive for carburetor ice at glide or cruise power.

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	54,Female
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	April 11, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	June 17, 2021
Flight Time:	1813.5 hours (Total, all aircraft), 215 hours (Total, this make and model), 1763 hours (Pilot In Command, all aircraft), 69.2 hours (Last 90 days, all aircraft), 28.5 hours (Last 30 days, all aircraft)		

Page 2 of 5 ANC23LA020

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N5987H
Model/Series:	PA-16	Aircraft Category:	Airplane
Year of Manufacture:	1946	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	16-615
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	January 18, 2023 Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	C126 installed, not activated	Engine Model/Series:	0-320
Registered Owner:	On file	Rated Power:	150 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PASX,113 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	16:56 Local	Direction from Accident Site:	68°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	Overcast / 6500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	60°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.87 inches Hg	Temperature/Dew Point:	-2°C / -8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Soldotna, AK	Type of Flight Plan Filed:	None
Destination:	Sterling, AK (88AK)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 3 of 5 ANC23LA020

Airport Information

Airport:	Soldotna Airport SXQ	Runway Surface Type:	Snow
Airport Elevation:	113 ft msl	Runway Surface Condition:	Snow
Runway Used:	07	IFR Approach:	None
Runway Length/Width:	5001 ft / 130 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	60.474864,-151.03964(est)

Page 4 of 5 ANC23LA020

Administrative Information

Investigator In Charge (IIC): Ward, Mark

Additional Participating Persons:

Original Publish Date: December 14, 2023

Last Revision Date:

Investigation Class: Class 3

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=106728

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 ANC23LA020