



Aviation Investigation Final Report

Location:	Livonia, New York	Accident Number:	ERA23LA157
Date & Time:	March 21, 2023, 13:30 Local	Registration:	N73905
Aircraft:	Bell 47G-2A-1	Aircraft Damage:	Substantial
Defining Event:	Abnormal runway contact	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

During a practice autorotation with a tail wind, the pilot began the maneuver and the helicopter initially lost airspeed; the pilot immediately corrected with forward cyclic input, which also increased his descent rate. The higher than normal descent rate continued, and he began the power recovery earlier than normal. Shortly before touchdown, the pilot noticed a slope in the terrain with the rising side to his aft. The helicopter continued to descend and the helicopter's tail rotor contacted the ground during the landing flare. The resulting impact resulted in a loss of control and substantial damage to the tail boom and tail rotor. The pilot stated that there were no preimpact malfunctions or failures of the helicopter that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's delayed action to arrest the high descent rate during a practice autorotation in tailwind conditions which ultimately resulted in loss of control.

Findings

Aircraft	Descent rate - Not attained/maintained
Personnel issues	Delayed action - Pilot

Factual Information

History of Flight

Landing-flare/touchdown	Abnormal runway contact (Defining event)
--------------------------------	--

Pilot Information

Certificate:	Airline transport	Age:	62, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	February 10, 2023
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 20000 hours (Total, all aircraft), 460 hours (Total, this make and model)		

Student pilot Information

Certificate:	Student	Age:	Male
Airplane Rating(s):	None	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 5 hours (Total, all aircraft), 0 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Bell	Registration:	N73905
Model/Series:	47G-2A-1	Aircraft Category:	Helicopter
Year of Manufacture:	1963	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2860
Landing Gear Type:	None; Skid	Seats:	3
Date/Type of Last Inspection:	July 3, 2022 Annual	Certified Max Gross Wt.:	2950 lbs
Time Since Last Inspection:	10 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	9400 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	VO-435
Registered Owner:	FROST HOLLOW HELICOPTER LLC	Rated Power:	220 Horsepower
Operator:	FROST HOLLOW HELICOPTER LLC	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ROC, 540 ft msl	Distance from Accident Site:	18 Nautical Miles
Observation Time:	13:54 Local	Direction from Accident Site:	347°
Lowest Cloud Condition:	Scattered / 9000 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	14 knots / 25 knots	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	260°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.3 inches Hg	Temperature/Dew Point:	11°C / -4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Livonia, NY	Type of Flight Plan Filed:	
Destination:	Livonia, NY	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	42.826067,-77.585174(est)

Administrative Information

Investigator In Charge (IIC):	Mccarter, Lawrence
Additional Participating Persons:	Anthony Luttrell; FAA/FSDO; Rochester, NY
Original Publish Date:	June 23, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=106929

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).