



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

Aviation Investigation Final Report

Location:	NEWARK, New Jersey	Incident Number:	DCA931A027
Date & Time:	March 4, 1993, 17:00 Local	Registration:	N99838
Aircraft:	AEROSPATIALE ATR42-300	Aircraft Damage:	None
Defining Event:		Injuries:	34 None
Flight Conducted Under:	Part 121: Air carrier - Scheduled		

Analysis

FLIGHT 3444 ENCOUNTERED SEVERE TURBULENCE AND ICING CONDITIONS WHILE ON APPROACH TO RUNWAY 4R AT NEWARK INTERNATIONAL AIRPORT. AN ANALYSIS OF THE WEATHER REVEALED THAT THERE WERE 'STRONG HORIZONTAL GUSTS' AND SEVERE TURBULENCE IN THE NEWARK AREA BELOW 5,000 FEET. ALSO, THE FLIGHTCREW STATED THAT THEY HAD BEEN FLYING IN ICING CONDITIONS THAT CONSISTED OF A MIXTURE OF RIME AND CLEAR ICE. THE CAPTAIN STATED THAT HE OBSERVED ABOUT 3 INCHES OF ICE ON TOP OF THE WING, BEHIND THE LEADING EDGE WING BOOT. APPROVED PROCEDURES FOR FLIGHT IN ICING CONDITIONS REQUIRE THE PROPELLER SPEED BE MAINTAINED AT 86 PERCENT OR HIGHER TO PREVENT UNEVEN ICE ACCUMULATION OF THE WING. THE DFDR INFORMATION REVEALED THE CREW HAD THE PROPELLER SPEED AT 77 PERCENT, 9 PERCENT THE REQUIRED MINIMUM.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this incident to be: THE FLIGHTCREW'S FAILURE TO FOLLOW APPROVED PROCEDURES THAT REQUIRED A MINIMUM PROPELLER SPPED WHILE FLYING IN ICING CONDITION. CONTRIBUTING TO THE LOSS OF ROLL CONTROL WERE THE ENCOUNTERS WITH SEVERE TURBULENCE AND ICING CONDITIONS.

Findings

Occurrence #1: ABRUPT MANEUVER

Phase of Operation: APPROACH

Findings

1. PROCEDURES/DIRECTIVES - NOT FOLLOWED - PILOT IN COMMAND
2. (C) THROTTLE/POWER CONTROL - IMPROPER USE OF - PILOT IN COMMAND
3. (F) WEATHER CONDITION - TURBULENCE IN CLOUDS
4. WEATHER CONDITION - ICING CONDITIONS
5. AIRCRAFT CONTROL - NOT POSSIBLE - PILOT IN COMMAND

Factual Information

ON MARCH 4, 1993, AT 1704 EASTERN STANDARD TIME , AN AEROSPATIALE ATR-42-300, N99838, REGISTERED TO BRITT AIRWAYS AND OPERATING AS CONTINENTAL EXPRESS FLIGHT 3444, EXPERIENCED AN IN-FLIGHT UPSET WHILE ON APPROACH TO NEWARK INTERNATIONAL AIRPORT, NEWARK, NEW JERSEY.

THE UPSET OCCURRED WHILE THE AIRPLANE WAS FLYING IN REPORTED "SEVERE" TURBULENCE AND ICING CONDITIONS.

THE FLIGHTCREW STATED THAT THEY ENCOUNTERED ICING CONDITIONS WHILE DESCENDING OVER YARDLEY INTERSECTION, ON THE APPROACH TO RUNWAY 4R AT NEWARK. THE FLIGHTCREW STATED THAT AIRFRAME ICE WAS BEING SHED FROM THE PROTECTED AREAS, BUT THEY ALSO NOTED THAT THERE WAS AN ACCUMULATION OF ICE ON TOP OF THE WING, AFT OF THE LEADING EDGE BOOT. THE CREW ALSO STATED THAT THEY HAD BEEN IN THE ICING CONDITIONS FOR APPROXIMATELY 10 TO 15 MINUTES.

THE CREW DESCRIBED THE ENVIRONMENTAL CONDITIONS AS CLOUDS TOPS BEING AT 10,000 TO 11,000 FEET, THE TEMPERATURE WAS ABOVE FREEZING AT ABOUT 3,000 FEET, HOWEVER, THEY WERE FLYING IN FREEZING RAIN CONDITIONS WHILE BEING VECTORED. THE ALTITUDES WHERE ICING CONDITIONS HAD BEEN ENCOUNTERED WERE BETWEEN 5,000 AND 11,000 FEET.

THE CAPTAIN DESCRIBED THE ICING CONDITIONS AS LIGHT TO OCCASIONAL MODERATE, AND THAT THERE WAS MIXED RIME AND CLEAR ICE. HE STATED THAT THE ICE ACCUMULATED TO ABOUT 3 INCHES AFT OF THE PROTECTED SURFACES, AND AS FAR AFT AS HE COULD SEE. THE ICE WAS OBSERVED TO BE ONLY ON TOP OF THE WING. IN ADDITION, THERE WAS MODERATE TURBULENCE IN THE ICING ENVIRONMENT, INCLUDING WINDSHEAR OF ABOUT 10 KNOTS.

THE DFDR REVEALED THAT WHILE THE AIRPLANE WAS ON APPROACH, THE AUTOPILOT HAD DISCONNECTED AND THE AIRPLANE ROLL ABOUT 48 DEGREES, RIGHT WING DOWN, WHILE AT A SPEED OF 168 KNOTS. THE INITIAL ROLL EXCURSION WAS FOLLOWED BY SEVERAL MORE THAT WERE RECORDED TO BE BETWEEN 22 AND 27 DEGREES RIGHT WING DOWN. THE LAST ROLL EVENT OCCURRING AT 190 KNOTS.

FURTHER INVESTIGATION OF THE FLIGHTCREW'S OPERATION OF THE AIRPLANE, AND INFORMATION REVEALED ON THE DFDR INDICATE THAT THE CREW HAD THE PROPELLER SPEED AT 77 PERCENT DURING THE FLIGHT IN ICING CONDITIONS. ACCORDING TO CONTINENTAL EXPRESS AND ATR, THE PROCEDURES FOR OPERATING IN ICING CONDITIONS REQUIRE THE PROPELLER SPEED TO BE AT 86 PERCENT OR HIGHER TO

REDUCE THE POSSIBILITY OF UNEVEN ICE ACCRETIONS ON 100 PERCENT OF THE AERODYNAMIC CHORD OF THE WING.

FURTHER EXAMINATION OF THE WEATHER REVEALED THAT "SEVERE TURBULENCE AND STRONG HORIZONTAL GUSTS" OCCURRED IN THE NEWARK AREA BELOW 5,000 FEET.

Pilot Information

Certificate:	Airline transport	Age:	Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	9000 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	AEROSPATIALE	Registration:	N99838
Model/Series:	ATR42-300 ATR42-300	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Transport	Serial Number:	
Landing Gear Type:	Retractable - Tricycle	Seats:	30
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	25000 lbs
Time Since Last Inspection:		Engines:	2 Turbo prop
Airframe Total Time:		Engine Manufacturer:	P&W
ELT:	Not installed	Engine Model/Series:	PW120
Registered Owner:	BRITT AIRWAYS	Rated Power:	1800 Horsepower
Operator:	BRITT AIRWAYS	Operating Certificate(s) Held:	Flag carrier (121)
Operator Does Business As:		Operator Designator Code:	BRIA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument (IMC)	Condition of Light:	Dusk
Observation Facility, Elevation:	EWR	Distance from Accident Site:	
Observation Time:	16:50 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	1.5 miles
Lowest Ceiling:	Broken / 1600 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	28 knots / 46 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	70°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	3°C / 1°C
Precipitation and Obscuration:			
Departure Point:	BALTIMORE (BWI)	Type of Flight Plan Filed:	IFR
Destination:		Type of Clearance:	IFR
Departure Time:	00:00 Local	Type of Airspace:	Class E

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	4R	IFR Approach:	ILS
Runway Length/Width:		VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	None
Passenger Injuries:	32 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	34 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC): Feith, Gregory

Additional Participating Persons:

Original Publish Date: August 21, 2001

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=10972>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).