



# **Aviation Investigation Final Report**

Location: MIDDLETOWN, Delaware Accident Number: BF085LA058

Date & Time: July 13, 1985, 19:15 Local Registration: N8577P

Aircraft: PIPER PA-24-260 Aircraft Damage: Substantial

**Defining Event:** 1 Serious

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

FOLLOWING TAKEOFF, AT ABOUT 350 FEET AGL, THE ENGINE QUIT ABRUPTLY. THE PLT ATTEMPTED TO LAND IN A FIELD WHICH WAS LOCATED ABOUT 15 DEGREES EAST OF THE ACFT'S HEADING. WHILE ATTEMPTING TO AVOID PWR LINES NEAR THE FIELD, THE RIGHT WING COLLIDED WITH THE WIRES. AFTER CONTACT WITH THE WIRES, WITNESS CONCUR THAT THE PLT WAS ABLE TO RAISE THE NOSE OF THE ACFT, BEFORE THE RIGHT WING STRUCK THE GROUND, FOLLOWED BY THE BOTTOM NOSE SECTION COWLING, NEAR THE NOSE WHEEL. AT THIS POINT, THE AIRCRAFT HAD PIVOTED ALMOST 180 DEGREES, AND BOUNCED BACKWARD THROUGH THE AIR APPROXIMATELY 60 FEET BEFORE COMING TO REST.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: TAKEOFF - INITIAL CLIMB

**Findings** 

1. (F) FLUID, FUEL - STARVATION

2. (C) FUEL TANK SELECTOR POSITION - IMPROPER - PILOT IN COMMAND

-----

Occurrence #2: FORCED LANDING

Phase of Operation: TAKEOFF - INITIAL CLIMB

------

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: DESCENT - EMERGENCY

Findings

3. (F) OBJECT - SOFT

-----

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Page 2 of 6 BF085LA058

## **Factual Information**

#### **Pilot Information**

| Certificate:              | Private  | Age:                              | 51,Male         |
|---------------------------|--|-----------------------------------|-----------------|
| Airplane Rating(s):       | Single-engine land; Multi-engine land  | Seat Occupied:                    | Left            |
| Other Aircraft Rating(s): | None   | Restraint Used:                   |                 |
| Instrument Rating(s):     | None   | Second Pilot Present:             | Yes             |
| Instructor Rating(s):     | None   | Toxicology Performed:             | No              |
| Medical Certification:    | Class 3 Valid Medicalw/<br>waivers/lim   | Last FAA Medical Exam:            | January 3, 1984 |
| Occupational Pilot:       | No   | Last Flight Review or Equivalent: |                 |
| Flight Time:              | 1477 hours (Total, all aircraft), 106 hours (Total, this make and model), 1413 hours (Pilot In Command, all aircraft), 8 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) |                                   |                 |

Page 3 of 6 BF085LA058

### **Aircraft and Owner/Operator Information**

| Aircraft Make:                   | PIPER                      | Registration:                     | N8577P          |
|----------------------------------|----------------------------|-----------------------------------|-----------------|
| Model/Series:                    | PA-24-260 PA-24-260        | Aircraft Category:                | Airplane        |
| Year of Manufacture:             |                            | Amateur Built:                    |                 |
| Airworthiness Certificate:       | Normal                     | Serial Number:                    | 24-4034         |
| Landing Gear Type:               | Retractable - Tricycle     | Seats:                            | 4               |
| Date/Type of Last<br>Inspection: | February 26, 1985 Annual   | Certified Max Gross Wt.:          | 2900 lbs        |
| Time Since Last Inspection:      | 8 Hrs                      | Engines:                          | 1 Reciprocating |
| Airframe Total Time:             | 4297 Hrs                   | Engine Manufacturer:              | LYCOMING        |
| ELT:                             | Installed, not activated   | Engine Model/Series:              | IO-540-E4A5     |
| Registered Owner:                | BAPTIST BIBLE CHURCH, INC. | Rated Power:                      | 260 Horsepower  |
| Operator:                        |                            | Operating Certificate(s)<br>Held: | None            |
| Operator Does Business As:       |                            | Operator Designator Code:         |                 |

## Meteorological Information and Flight Plan

| Conditions at Accident Site:     | Visual (VMC)              | Condition of Light:                  | Day               |
|----------------------------------|---------------------------|--------------------------------------|-------------------|
| Observation Facility, Elevation: | ILG ,80 ft msl            | Distance from Accident Site:         | 12 Nautical Miles |
| Observation Time:                | 18:51 Local               | Direction from Accident Site:        | 30°               |
| <b>Lowest Cloud Condition:</b>   | Clear                     | Visibility                           | 8 miles           |
| Lowest Ceiling:                  | None                      | Visibility (RVR):                    |                   |
| Wind Speed/Gusts:                | 8 knots /                 | Turbulence Type<br>Forecast/Actual:  | /                 |
| Wind Direction:                  | 170°                      | Turbulence Severity Forecast/Actual: | /                 |
| Altimeter Setting:               | 30 inches Hg              | Temperature/Dew Point:               | 31°C / 18°C       |
| Precipitation and Obscuration:   | N/A - None - Haze         |                                      |                   |
| Departure Point:                 | MIDDLETOWN , DE (N92<br>) | Type of Flight Plan Filed:           | None              |
| Destination:                     |                           | Type of Clearance:                   | None              |
| Departure Time:                  | 07:10 Local               | Type of Airspace:                    | Class G           |
|                                  |                           |                                      |                   |

Page 4 of 6 BF085LA058

#### **Airport Information**

| Airport:             |             | Runway Surface Type:             |                |
|----------------------|-------------|----------------------------------|----------------|
| Airport Elevation:   | 0 ft msl    | <b>Runway Surface Condition:</b> |                |
| Runway Used:         | 0           | IFR Approach:                    | None           |
| Runway Length/Width: | 0 ft / 0 ft | VFR Approach/Landing:            | Forced landing |

## Wreckage and Impact Information

| Crew Injuries:         | 1 Serious | Aircraft Damage:        | Substantial             |
|------------------------|-----------|-------------------------|-------------------------|
| Passenger<br>Injuries: |           | Aircraft Fire:          | None                    |
| Ground Injuries:       | N/A       | Aircraft Explosion:     | None                    |
| Total Injuries:        | 1 Serious | Latitude,<br>Longitude: | 39.450263,-75.7098(est) |

Page 5 of 6 BF085LA058

#### **Administrative Information**

| Investigator In Charge (IIC):     | Dickinson, Al                                |
|-----------------------------------|--|
|                                   |  |
| Additional Participating Persons: |  |
| Original Publish Date:            |  |
| Last Revision Date:               |  |
| Investigation Class:              | <u>Class</u>                                 |
| Note:                             |  |
| Investigation Docket:             | https://data.ntsb.gov/Docket?ProjectID=11184 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 BF085LA058