

# **Aviation Investigation Final Report**

Location:	QUINTON, Virginia	Accident Number:	BF091LA051
Date & Time:	May 26, 1991, 11:45 Local	<b>Registration:</b>	N949Z
Aircraft:	Smith, Ted Aerostar STP1	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

### **Analysis**

THE PILOT WAS TAXIING ON THE RAMP HEADED TOWARD THE PARALLEL TAXIWAY FOR RUNWAY 28, WHEN HIS AIRPLANE WAS STRUCK IN THE REAR BY ANOTHER MOVING AIRPLANE. THE PILOT STATED HE DID NOT SEE THE AIRPLANE BEFORE IMPACT.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT OF THE OTHER AIRCRAFT FAILED TO MAINTAIN ADEQUATE CLEARANCE.

### **Findings**

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: TAXI - TO TAKEOFF

Findings

1. (F) OBJECT - AIRCRAFT MOVING ON GROUND

2. (C) CLEARANCE - NOT MAINTAINED - PILOT OF OTHER AIRCRAFT

# **Factual Information**

### **Pilot Information**

Certificate:	Private	Age:	58,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	750 hours (Total, all aircraft)		

### Aircraft and Owner/Operator Information

Aircraft Make:	Smith, Ted Aerostar	Registration:	N949Z
Model/Series:	STP1 STP1	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Experimental (Special)	Serial Number:	1ST64
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	January 2, 2000 Unknown	Certified Max Gross Wt.:	900 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:		Engine Model/Series:	O 290 D2
Registered Owner:	WALTER K. CRAWFORD	Rated Power:	150 Horsepower
Operator:	WALTER K. CRAWFORD, JR.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:	11:45 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 25000 ft AGL	Visibility	7 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	32°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	(W96)	Type of Flight Plan Filed:	None
Destination:	(W96)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

## **Airport Information**

Airport:	NEW KENT COUNTY W95	Runway Surface Type:	Asphalt
Airport Elevation:	123 ft msl	Runway Surface Condition:	Dry
Runway Used:	28	IFR Approach:	
Runway Length/Width:	3600 ft / 75 ft	VFR Approach/Landing:	

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.530776,-77.109893(est)

### **Administrative Information**

Investigator In Charge (IIC):	Jones, Dennis		
Additional Participating Persons:	JOHN DOSTAL; RICHMOND , VA		
Original Publish Date:	March 31, 1993		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=11678		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.



# **Aviation Investigation Final Report**

Location:	QUINTON, Virginia		Accident Number:	BF091LA051
Date & Time:	May 26, 1991, 11:4	5 Local	<b>Registration:</b>	N38272
Aircraft:	PIPER	J3C 65	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General av	viation - Personal		

### Analysis

THE PILOT WAS TAXIING IN THE RAMP AREA HEADED TOWARD THE PARALLEL TAXIWAY FOR RUNWAY 28 WHEN HE STRUCK THE REAR OF ANOTHER MOVING AIRPLANE, A SMITH STP1 BIPLANE. THE PILOT REPORTED THAT HE DID NOT SEE THE AIRPLANE BEFORE THE IMPACT. THE RIGHT WING STRUT STRUCK THE OTHER AIRPLANE'S RUDDER AND THEN ITS AFT SECTION WITH THE PROPELLER.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN ADEQUATE CLEARANCE FROM A MOVING AIRCRAFT.

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: TAXI - TO TAKEOFF

Findings

1. (F) OBJECT - AIRCRAFT MOVING ON GROUND

2. (C) CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

## **Factual Information**

### **Pilot Information**

Certificate:	Private	Age:	43,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1600 hours (Total, all aircraft)		

### Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N38272
Model/Series:	J3C 65 J3C 65	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	6898
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	January 2, 2000 Unknown	Certified Max Gross Wt.:	1220 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	A65
Registered Owner:	PETER W. WOMACK	Rated Power:	65 Horsepower
Operator:	PETER W. WOMACK	Operating Certificate(s) Held:	None
<b>Operator Does Business As:</b>		Operator Designator Code:	

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:	11:45 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 25000 ft AGL	Visibility	7 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	32°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	(W96)	Type of Flight Plan Filed:	None
Destination:	(W96)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

## **Airport Information**

Airport:	NEW KENT COUNTY W95	Runway Surface Type:	Asphalt
Airport Elevation:	123 ft msl	Runway Surface Condition:	Dry
Runway Used:	28	IFR Approach:	
Runway Length/Width:	3600 ft / 75 ft	VFR Approach/Landing:	

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.530776,-77.109893(est)

### **Administrative Information**

Investigator In Charge (IIC):	Jones, Dennis		
Additional Participating Persons:	JOHN DOSTAL; RICHMOND , VA		
Original Publish Date:	March 31, 1993		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=11678			

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.