



Aviation Investigation Final Report

Location: DOYLESTOWN, Pennsylvania Accident Number: BFO92LA041

Date & Time: March 16, 1992, 13:30 Local Registration: N872RJ

Aircraft: PIPER PA-46-350P Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

DURING TOUCHDOWN ON RUNWAY 23 AT DOYLESTOWN AIRPORT, DOYLESTOWN, PENNSYLVANIA, THE AIRPLANE ENCOUNTERED A TURBULENT GUST OF WIND AND THE RIGHT WING ROSE ABRUPTLY. THE PILOT STATED THAT EVEN THOUGH HE INPUT FULL AILERON AND ALMOST FULL RUDDER, THE AIRPLANE VEERED OFF THE LEFT OF THE RUNWAY AND IMPACTED A WIND SOCK POLE AND WIND TEE. THERE WAS NO REPORTED AIRFRAME OR ENGINE MALFUNCTION PRIOR TO HITTING THE WIND SOCK POLE. THE PILOT WAS NOT INJURED, BUT THE AIRPLANE WAS SUBSTANTIALLY DAMAGED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FAILURE OF THE PILOT TO MAINTAIN DIRECTIONAL CONTROL DURING TOUCHDOWN, WHICH RESULTED IN AN INADVERTENT GROUND SWERVE. A FACTOR RELATED TO THE ACCIDENT WAS THE GUSTY CROSSWIND CONDITION.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (F) WEATHER CONDITION - GUSTS

3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND 4. (C) GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings

5. OBJECT - POLE

Page 2 of 6 BF092LA041

Factual Information

Pilot Information

Certificate:	Private	Age:	45,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 25, 1991
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1149 hours (Total, all aircraft), 408 hours (Total, this make and model), 971 hours (Pilot In Command, all aircraft), 27 hours (Last 90 days, all aircraft), 21 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

Page 3 of 6 BF092LA041

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N872RJ
Model/Series:	PA-46-350P PA-46-350P	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	4622028
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	June 13, 1992 Annual	Certified Max Gross Wt.:	4318 lbs
Time Since Last Inspection:	84 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	464 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	TIO-540-AE2A
Registered Owner:	GULL LEASING INCORPORATED	Rated Power:	350 Horsepower
Operator:	RAYMOND J. CAWLEY	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ABE ,1 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	13:51 Local	Direction from Accident Site:	1°
Lowest Cloud Condition:	Clear	Visibility	30 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	16 knots / 20 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	0°C / -16°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	CHARLESTON (CHS)	Type of Flight Plan Filed:	VFR/IFR
Destination:		Type of Clearance:	VFR;IFR
Departure Time:	10:30 Local	Type of Airspace:	Class G

Page 4 of 6 BF092LA041

Airport Information

Airport:	DOYLESTOWN AIRPORT N88	Runway Surface Type:	Asphalt
Airport Elevation:	394 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	
Runway Length/Width:	3004 ft / 60 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	40.310626,-75.120536(est)

Page 5 of 6 BF092LA041

Administrative Information

Investigator In Charge (IIC):	Napolitan, Margaret	
Additional Participating Persons:	M. PLANTS; ALLENTOWN , PA	
Original Publish Date:	August 13, 1993	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=11772	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 BFO92LA041