



Aviation Investigation Final Report

Location:	EAST LIVERPOOL, Ohio	Accident Number:	CHI83LA211
Date & Time:	May 13, 1983, 15:25 Local	Registration:	N5512Y
Aircraft:	PIPER PA-23-250	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

DURING THE APPROACH, THE PLT NEGLECTED TO EXTEND THE GEAR, AAND SUBSEQUENTLY, MADE A WHEELS UP LANDING.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) GEAR EXTENSION - NOT PERFORMED - PILOT IN COMMAND
2. (F) WHEELS UP LANDING - INADVERTENT - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	58, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	April 26, 1983
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	3700 hours (Total, all aircraft), 36 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N5512Y
Model/Series:	PA-23-250 PA-23-250	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	27-2608
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	April 1, 1983 Annual	Certified Max Gross Wt.:	5200 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	3150 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	IO-540-C4B5
Registered Owner:	TRU-LITE INTERNATIONAL INC.	Rated Power:	250 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	BUTLER , PA (BTP)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	COLUMBIANA CO. 02G	Runway Surface Type:	Asphalt
Airport Elevation:	1160 ft msl	Runway Surface Condition:	Dry
Runway Used:	6	IFR Approach:	None
Runway Length/Width:	3512 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	40.629112,-80.560829(est)

Administrative Information

Investigator In Charge (IIC): Dinwiddie, Carlq

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.ntsb.gov/Docket?ProjectID=12172>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).