



Aviation Investigation Final Report

Location: CHICAGO, Illinois Incident Number: CHI89IA145

Date & Time: July 9, 1989, 12:47 Local Registration: N265MC

Aircraft: DORNIER DO-228 Aircraft Damage: None

Defining Event: 9 None

Flight Conducted Under: Part 135: Air taxi & commuter - Scheduled

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this incident to be: POOR LOOKOUT BY THE CREW OF THE DORNIER AND THE CITABRIA.

Findings

Factual Information

History of Flight

Pilot Information

Certificate: Airline transport; Flight engineer Age: Male Airplane Rating(s): Single-engine land; Multi-engine land; Multi-engine land Seat Occupied: Left Other Aircraft Rating(s): None Restraint Used: Instrument Rating(s): Airplane Second Pilot Present: Yes Instructor Rating(s): None Toxicology Performed: No				
Other Aircraft Rating(s): None Restraint Used: Instrument Rating(s): Airplane Second Pilot Present: Yes	Certificate:	Airline transport; Flight engineer	Age:	Male
Instrument Rating(s): Airplane Second Pilot Present: Yes	Airplane Rating(s):	3 3 ,	Seat Occupied:	Left
	Other Aircraft Rating(s):	None	Restraint Used:	
Instructor Rating(s): None Toxicology Performed: No	Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
5.,	Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification: Class 1 Valid Medical-no Last FAA Medical Exam: waivers/lim.	Medical Certification:		Last FAA Medical Exam:	
Occupational Pilot: Yes Last Flight Review or Equivalent:	Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	DORNIER	Registration:	N265MC
Model/Series:	DO-228 DO-228	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Transport	Serial Number:	
Landing Gear Type:	Retractable - Tricycle	Seats:	20
Date/Type of Last Inspection:	Continuous airworthiness	Certified Max Gross Wt.:	7700 lbs
Time Since Last Inspection:		Engines:	2 Turbo prop
Airframe Total Time:		Engine Manufacturer:	GARRETT
ELT:	Not installed	Engine Model/Series:	TPE 331-5
Registered Owner:	MIDWAY AIRLINES	Rated Power:	715 Horsepower
Operator:		Operating Certificate(s) Held:	Commuter air carrier (135)
Operator Does Business As:		Operator Designator Code:	MIWA

Page 2 of 4 CHI89IA145

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DPA ,758 ft msl	Distance from Accident Site:	15 Nautical Miles
Observation Time:	14:45 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered	Visibility	3 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	12 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	36°C / 22°C
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	ROCKFORD , IL (RFD)	Type of Flight Plan Filed:	IFR
Destination:		Type of Clearance:	IFR
Departure Time:	00:00 Local	Type of Airspace:	Class A;Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	None
Passenger Injuries:	7 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	9 None	Latitude, Longitude:	

Page 3 of 4 CHI89IA145

Administrative Information

Investigator In Charge (IIC):

Additional Participating
Persons:

Original Publish Date:

Last Revision Date:

Investigation Class:

Note:

Investigation Docket:

https://data.ntsb.gov/Docket?ProjectID=14288

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 CHI89IA145