

# **Aviation Investigation Final Report**

Location:	INDIANAPOLIS, Ind	diana	Accident Number:	CHI89LA130
Date & Time:	July 9, 1989, 20:00	Local	Registration:	N2545A
Aircraft:	PIPER	PA-38-112	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Instructional			

### **Analysis**

THE STUDENT PLT ON A SOLO FLT WAS ATTEMPTING A TOUCH-AND-GO LANDING, FLARED HIGH AND BOUNCED. HE ATTEMPTED TO RECOVER FROM THE BOUNCED LANDING WITH A POWER ADDITION AND REDUCTION. WHEN HE SAW HE WAS GOING TO BOUNCE AGAIN, HE MADE TWO ADDITIONAL POWER APPLICATIONS AND REDUCTIONS. HE LOST DIRECTIONAL CONTROL TO THE LEFT WHEN THE LEFT WHEEL TOUCHED DOWN ON THE RUNWAY WITH FULL POWER ON THE AIRCRAFT. HE LANDED OFF THE RUNWAY AND STRUCK A FENCE POST WITH THE RIGHT WING. THE STUDENT HAD 6 HOURS SOLO TIME AT THE TIME OF THE ACCIDENT.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: IMPROPER RECOVERY FROM A BOUNCED LANDING AND FAILURE TO MAINTAIN DIRECTIONAL CONTROL BY THE PILOT. THE STUDENT PILOT'S LACK OF FLIGHT EXPERIENCE CONTRIBUTED TO THE ACCIDENT.

#### Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING

Findings 1. TOUCH-AND-GO - PERFORMED - PILOT IN COMMAND 2. (F) LACK OF TOTAL EXPERIENCE - PILOT IN COMMAND
3. (F) FLARE - MISJUDGED - PILOT IN COMMAND
4. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND
5. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: LANDING - ABORTED

Findings 6. OBJECT - FENCE POST

## **Factual Information**

#### **Pilot Information**

Certificate:	Student	Age:	42,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	May 30, 1989
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	30 hours (Total, all aircraft), 24 hours (Total, this make and model), 6 hours (Pilot In Command, all aircraft), 29 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

#### Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N2545A
Model/Series:	PA-38-112 PA-38-112	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	38-7A0746
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	May 20, 1989 100 hour	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	89 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2530 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-235-L2C
Registered Owner:	GREENWOOD FLITE CENTER INC	Rated Power:	112 Horsepower
Operator:	GREENWOOD FLIGHT CENTER	Operating Certificate(s) Held:	None
Operator Does Business As:	GREENWOOD FLIGHT CENTER	Operator Designator Code:	

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	IND ,797 ft msl	Distance from Accident Site:	11 Nautical Miles
Observation Time:	19:50 Local	Direction from Accident Site:	320°
Lowest Cloud Condition:	Clear	Visibility	3 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	28°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	19:50 Local	Type of Airspace:	Class G

#### **Airport Information**

Airport:	GREENWOOD MUNI. SI1	Runway Surface Type:	Asphalt
Airport Elevation:	830 ft msl	Runway Surface Condition:	Dry
Runway Used:	18	IFR Approach:	None
Runway Length/Width:	3475 ft / 50 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.670509,-86.130653(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Doub, Mark	
Additional Participating Persons:	BILL DEVINE; INDIANAPOLIS, IN	
Original Publish Date:	October 24, 1990	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=14378	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.