



Aviation Investigation Final Report

Location: BIG RAPIDS, Michigan Accident Number: CHI91LA165

Date & Time: May 23, 1991, 19:30 Local Registration: N7209Y

Aircraft: PIPER PA-30 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

THE PRIVATE RATED PILOT WAS ON A DUAL MULTIENGINE INSTRUCTIONAL FLIGHT. ON A PRACTICE SOFT-FIELD TAKEOFF THE AIRCRAFT BEGAN TO PULL TO THE LEFT WHEN THE AIRCRAFT WAS ROTATED. THE STUDENT CORRECTED WITH APPLICATION OF RIGHT RUDDER AND AILERON. THE RIGHT WING OF THE AIRCRAFT STRUCK THE RUNWAY.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: EXCESSIVE APPLICATION OF THE FLIGHT CONTROLS BY THE STUDENT PILOT. A FACTOR RELATED TO THE ACCIDENT IS DELAYED REMEDIAL ACTION BY THE FLIGHT INSTRUCTOR.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: TAKEOFF

Findings

1. TERRAIN CONDITION - RUNWAY

2. (C) FLIGHT CONTROLS - EXCESSIVE - DUAL STUDENT

3. (F) REMEDIAL ACTION - DELAYED - PILOT IN COMMAND(CFI)

Factual Information

Pilot Information

| Certificate: | Commercial; Flight instructor | Age: | 55,Male |
|---------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|------------------|
| Airplane Rating(s): | Single-engine land; Single-engine sea; Multi-engine land | Seat Occupied: | Right |
| Other Aircraft Rating(s): | Glider | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | Yes |
| Instructor Rating(s): | Airplane multi-engine; Airplane single-engine; Glider; Instrument airplane | Toxicology Performed: | No |
| Medical Certification: | Class 2 Valid Medical–w/ waivers/lim | Last FAA Medical Exam: | October 12, 1990 |
| Occupational Pilot: | UNK | Last Flight Review or Equivalent: | |
| Flight Time: | 2092 hours (Total, all aircraft), 142 hours (Total, this make and model), 1853 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft), 13 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) | | |

Page 2 of 5 CHI91LA165

Aircraft and Owner/Operator Information

| Aircraft Make: | PIPER | Registration: | N7209Y |
|-------------------------------|--------------------------------------------------------|-----------------------------------|-----------------|
| Model/Series: | PA-30 PA-30 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 30-235 |
| Landing Gear Type: | Retractable - Tricycle | Seats: | 4 |
| Date/Type of Last Inspection: | January 2, 2000 Unknown | Certified Max Gross Wt.: | 3725 lbs |
| Time Since Last Inspection: | | Engines: | 2 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | LYCOMING |
| ELT: | Installed, activated, did not aid in locating accident | Engine Model/Series: | IO-320-B1A |
| Registered Owner: | | Rated Power: | 160 Horsepower |
| Operator: | MECOSTA CTY PILOTS ASSN. | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |
| | | | |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|-------------------|
| Observation Facility, Elevation: | GRR ,794 ft msl | Distance from Accident Site: | 50 Nautical Miles |
| Observation Time: | 18:50 Local | Direction from Accident Site: | 180° |
| Lowest Cloud Condition: | Scattered / 2500 ft AGL | Visibility | 7 miles |
| Lowest Ceiling: | Overcast / 12000 ft AGL | Visibility (RVR): | |
| Wind Speed/Gusts: | 8 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 200° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30 inches Hg | Temperature/Dew Point: | 26°C / 21°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | | Type of Flight Plan Filed: | None |
| Destination: | | Type of Clearance: | None |
| Departure Time: | 18:30 Local | Type of Airspace: | |

Page 3 of 5 CHI91LA165

Airport Information

| Airport: | ROBEN-HOOD 77D | Runway Surface Type: | Asphalt |
|----------------------|-----------------|----------------------------------|---------|
| Airport Elevation: | 945 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 27 | IFR Approach: | |
| Runway Length/Width: | 4300 ft / 75 ft | VFR Approach/Landing: | |

Wreckage and Impact Information

| Crew Injuries: | 2 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|--------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 43.69952,-85.479263(est) |

Page 4 of 5 CHI91LA165

Administrative Information

Investigator In Charge (IIC): Doub, Mark

Additional Participating Persons:

Original Publish Date: December 4, 1992

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=15072

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CHI91LA165