



Aviation Investigation Final Report

Location: BISMARCK, North Dakota Accident Number: CHI93LA128

Date & Time: March 10, 1993, 22:22 Local Registration: N88384

Aircraft: BELLANCA 7GCBC Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT DEPARTED GRAND ISLAND WITH FULL FUEL AND CALCULATIONS INDICATED AN EN ROUTE FUEL STOP WOULD BE REQUIRED. WHILE EN ROUTE, THE PILOT RECALCULATED THE FUEL CONSUMPTION AND ELECTED NOT TO MAKE THE FUEL STOP BUT TO CONTINUE TO THE DESTINATION. FUEL EXHAUSTION OCCURRED DURING THE LANDING APPROACH AT THE DESTINATION AIRPORT. A FORCED LANDING WAS MADE ON A ROAD DURING WHICH THE RIGHT WING CONTACTED A TREE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO REFUEL THE AIRPLANE EN ROUTE TO ENSURE ADEQUATE FUEL TO COMPLETE THE FLIGHT.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: APPROACH

Findings

1. FLUID, FUEL - EXHAUSTION

- 2. FUEL SUPPLY INADEQUATE PILOT IN COMMAND
- 3. (F) FUEL CONSUMPTION CALCULATIONS INACCURATE PILOT IN COMMAND
- 4. (C) REFUELING NOT PERFORMED PILOT IN COMMAND

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Findings

5. (F) LIGHT CONDITION - BRIGHT NIGHT

Occurrence #3: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings

6. (F) OBJECT - TREE(S)

Page 2 of 5 CHI93LA128

Factual Information

Pilot Information

Certificate:	Commercial	Age:	45,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	February 4, 1993
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1000 hours (Total, all aircraft), 251 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELLANCA	Registration:	N88384
Model/Series:	7GCBC 7GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	774-75
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	January 2, 2000 100 hour	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	0-320
Registered Owner:	LEROY E. NIELSEN	Rated Power:	150 Horsepower
Operator:	LEROY E. NIELSEN	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 CHI93LA128

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night/bright
Observation Facility, Elevation:	BIS ,1677 ft msl	Distance from Accident Site:	3 Nautical Miles
Observation Time:	21:50 Local	Direction from Accident Site:	310°
Lowest Cloud Condition:	Clear	Visibility	12 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	-8°C / -9°C
Precipitation and Obscuration:	No Obscuration; No Precipita	tion	
Departure Point:	GRAND ISLAND , NE (GRI)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	18:20 Local	Type of Airspace:	Class D

Airport Information

Airport:	BISMARCK MUNICIPAL BIS	Runway Surface Type:	
Airport Elevation:	1677 ft msl	Runway Surface Condition:	
Runway Used:	31	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	46.819881,-100.700851(est)

Page 4 of 5 CHI93LA128

Administrative Information

Investigator In Charge (IIC):

Additional Participating Persons:

Original Publish Date:

November 3, 1993

Last Revision Date:

Investigation Class:

Class

Note:

Investigation Docket:

https://data.ntsb.gov/Docket?ProjectID=15693

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 CHI93LA128