



Aviation Investigation Final Report

Location: WALL, South Dakota Accident Number: DEN84LA099

Date & Time: January 27, 1984, 08:30 Local Registration: N7406B

Aircraft: CHAMPION 7EC Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE ACFT CRASHED DURING A FLIGHT FOR THE PURPOSE OF OBSERVING THE PLT'S CATTLE. THE PLT STATED HE WAS 'MAKING A STEEP LEFT TURN AT ABOUT 75 FEET AND THE BOTTOM (LEFT) WING FLEW INTO A WIND SHEAR ON THE DOWNWARD SIDE OF A HILL. THE AIRPLANE SLID TO THE LEFT AND STALLED.'

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: CRUISE - NORMAL

Findings

1. (F) WEATHER CONDITION - WINDSHEAR

2. (F) PROPER ALTITUDE - NOT MAINTAINED - PILOT IN COMMAND

3. (F) STALL - PERFORMED - PILOT IN COMMAND

4. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	28,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	November 19, 1983
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	286 hours (Total, all aircraft), 240 hours (Total, this make and model), 2589 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CHAMPION	Registration:	N7406B
Model/Series:	7EC 7EC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	7EC-438
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	March 18, 1983 100 hour	Certified Max Gross Wt.:	1220 lbs
Time Since Last Inspection:	44 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated	Engine Model/Series:	C90-12F
Registered Owner:	G.E. SHEARER	Rated Power:	90 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 DEN84LA099

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	330°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-1°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	08:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:
Airport Elevation:		Runway Surface Condition:
Runway Used:	0	IFR Approach:
Runway Length/Width:		VFR Approach/Landing:

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	43.990108,-102.230712(est)

Page 3 of 4 DEN84LA099

Administrative Information

Investigator In Charge (IIC):	Mucho, Gary
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=16343

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 DEN84LA099