



# **Aviation Investigation Final Report**

Location: KINDRED, North Dakota Accident Number: DEN84LA262

Date & Time: August 22, 1984, 09:15 Local Registration: N96168

Aircraft: HILLER UH-12C Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

THE PRACTICE AUTOROTATION TO TOUCHDOWN BEGAN AT 500 FT AGL. SHORTLY AFTER INITIATING THE FLARE THE TAIL ROTOR CONTACTED THE GROUND. THE PILOT WAS SCHEDULED FOR A PRIVATE PILOT HELICOPTER CHECK RIDE ON THE AFTERNOON OF THE ACCIDENT.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT

#### **Findings**

1. AUTOROTATION - SIMULATED - PILOT IN COMMAND

2. (C) FLARE - IMPROPER - PILOT IN COMMAND

3. (F) LACK OF TOTAL EXPERIENCE IN TYPE OF AIRCRAFT - PILOT IN COMMAND

4. TERRAIN CONDITION - GROUND

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial	Age:	37.Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical–w/ waivers/lim	Last FAA Medical Exam:	August 23, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	7547 hours (Total, all aircraft), 38 hours (Total, this make and model), 7410 hours (Pilot In Command, all aircraft), 166 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	HILLER	Registration:	N96168
Model/Series:	UH-12C UH-12C	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	55-4129
Landing Gear Type:	Skid	Seats:	4
Date/Type of Last Inspection:	May 2, 1984 100 hour	Certified Max Gross Wt.:	2500 lbs
Time Since Last Inspection:	91 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3502 Hrs	Engine Manufacturer:	FRANKLIN
ELT:	Not installed	Engine Model/Series:	O-335-6D
Registered Owner:	HEUER, DAN	Rated Power:	200 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 DEN84LA262

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	FAR ,900 ft msl	Distance from Accident Site:	29 Nautical Miles
Observation Time:	08:50 Local	Direction from Accident Site:	20°
<b>Lowest Cloud Condition:</b>	Scattered / 1700 ft AGL	Visibility	15 miles
Lowest Ceiling:	Broken / 3300 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	12°C / 7°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	KINDRED , ND (1ND3)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	08:45 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	HAMRY 1ND3	Runway Surface Type:	Grass/turf
Airport Elevation:		<b>Runway Surface Condition:</b>	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Simulated forced landing

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	46.65097,-97.020835(est)

Page 3 of 4 DEN84LA262

#### **Administrative Information**

Investigator In Charge (IIC): Scott, Arnold

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=16464

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 DEN84LA262