



Aviation Investigation Final Report

Location: LONGMONT, Colorado Accident Number: DEN86LA097

Date & Time: March 10, 1986, 15:15 Local Registration: N3280F

Aircraft: MOONEY M20F Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

ACCORDING TO THE PLT, DURING THE FLARE TO TOUCHDOWN, THE ACFT STALLED AND THE LEFT WING CONTACTED THE GROUND ALONG WITH FOUR RUNWAY LIGHTS. THE PLT SAID THE ACCIDENT COULD HAVE BEEN PREVENTED BY MAINTAINING A HIGHER AIRSPEED ON APCH.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND

2. (C) STALL - INADVERTENT - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Factual Information

Pilot Information

Certificate:	Private	Age:	47,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	December 11, 1985
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	908 hours (Total, all aircraft), 531 hours (Total, this make and model), 800 hours (Pilot In Command, all aircraft), 26 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	MOONEY	Registration:	N3280F
Model/Series:	M20F M20F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	670373
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	July 12, 1985 100 hour	Certified Max Gross Wt.:	2740 lbs
Time Since Last Inspection:	72 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1752 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-360-A1A
Registered Owner:	ORVILLE G. ANDERSON, JR.	Rated Power:	200 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 DEN86LA097

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
	Distance from Accident Site:	
	Direction from Accident Site:	
Scattered / 5000 ft AGL	Visibility	20 miles
None	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	/
0°	Turbulence Severity Forecast/Actual:	/
	Temperature/Dew Point:	12°C
No Obscuration; No Precipita	tion	
BROOMFIELD , CO (BJC)	Type of Flight Plan Filed:	None
	Type of Clearance:	None
15:05 Local	Type of Airspace:	Class D
	Scattered / 5000 ft AGL None / 0° No Obscuration; No Precipita BROOMFIELD , CO (BJC)	Distance from Accident Site: Direction from Accident Site: Scattered / 5000 ft AGL Visibility None Visibility (RVR): / Turbulence Type Forecast/Actual: Turbulence Severity Forecast/Actual: Temperature/Dew Point: No Obscuration; No Precipitation BROOMFIELD , CO (BJC) Type of Flight Plan Filed: Type of Clearance:

Airport Information

Airport:	LONGMONT MUNICIPAL 2V2	Runway Surface Type:	Asphalt
Airport Elevation:	5055 ft msl	Runway Surface Condition:	Dry
Runway Used:	29	IFR Approach:	None
Runway Length/Width:	4200 ft / 60 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	40.169506,-105.110122(est)

Page 3 of 4 DEN86LA097

Administrative Information

Investigator In Charge (IIC): Mickle, Ronald

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=16936

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 DEN86LA097