



Aviation Investigation Final Report

Location: EUREKA, South Dakota Accident Number: DEN87LA053

Date & Time: February 10, 1987, 20:00 Local Registration: N3451X

Aircraft: MOONEY M20C Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

AFTER NORMAL TAKEOFF, THE ACFT CONTACTED THE TERRAIN THEN CONTINUED ON UNTIL IT CAME TO REST APRX 350' FROM THE INITIAL IMPACT POINT. THE LANDING GEAR HAD BEEN RETRACTED AT THE TIME OF INITIAL IMPACT AND THE PLT HAD NO INDICATION OF ANY MALFUNCTION/FAILURE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) AIRCRAFT HANDLING - IMPROPER - PILOT IN COMMAND

2. (F) LIGHT CONDITION - NIGHT

3. (C) PROPER CLIMB RATE - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	50,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	November 6, 1986
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	2658 hours (Total, all aircraft), 221 hours (Total, this make and model), 2658 hours (Pilot In Command, all aircraft), 27 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	MOONEY	Registration:	N3451X
Model/Series:	M20C M20C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	3409
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	September 25, 1986 Annual	Certified Max Gross Wt.:	2575 lbs
Time Since Last Inspection:	66 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2658 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	0-360-A1D
Registered Owner:	RICHARD S. ISAAK	Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 DEN87LA053

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Night/dark
MBG ,1715 ft msl	Distance from Accident Site:	43 Nautical Miles
20:00 Local	Direction from Accident Site:	240°
Clear	Visibility	12 miles
None	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	/
0°	Turbulence Severity Forecast/Actual:	/
29 inches Hg	Temperature/Dew Point:	-2°C / -4°C
No Obscuration; No Precipitation		
	Type of Flight Plan Filed:	None
MOBRIDGE , SD (MBG)	Type of Clearance:	None
19:55 Local	Type of Airspace:	Class G
	MBG ,1715 ft msl 20:00 Local Clear None / 0° 29 inches Hg No Obscuration; No Precipital	MBG ,1715 ft msl Distance from Accident Site: 20:00 Local Direction from Accident Site: Clear Visibility None Visibility (RVR): / Turbulence Type Forecast/Actual: 0° Turbulence Severity Forecast/Actual: 29 inches Hg Temperature/Dew Point: No Obscuration; No Precipitation Type of Flight Plan Filed: MOBRIDGE , SD (MBG) Type of Clearance:

Airport Information

Airport:		Runway Surface Type:	Dirt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	45.759086,-99.619621(est)

Page 3 of 4 DEN87LA053

Administrative Information

Investigator In Charge (IIC):	Collins, Robert	
Additional Participating Persons:	MARK GOODWIN; , SD DICK BRANDIGER; , SD	
Original Publish Date:	March 10, 1988	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=17168	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 DEN87LA053