



# **Aviation Investigation Final Report**

Location: ENGLEWOOD, Colorado Accident Number: DEN88DTE06

Date & Time: July 1, 1988, 12:35 Local Registration: N250TH

Aircraft: HELFRICH-LEONARD BD- Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

THIS EXPERIMENTAL ACFT IS POWERED BY A MODIFIED HONDA 1250 CC, WATERCOOLED ENG. THE PLT REPORTED THAT AFTER TAKEOFF THE ENG TEMP REACHED THE REDLINE AND THE ENG LOST POWER. DURING THE FORCED LANDING THE MAIN LANDING GEAR COLLAPSED. EXAMINATION OF THE ENG AFTER THE ACDT REVEALED THAT A HOLE WAS BURNED IN THE #4 PISTON AND A PORTION OF THE HEAD GASKET BETWEEN THE #3 AND #4 CYL WAS MISSING. THE OWNER AND TECHNICIANS FAMILIAR WITH THE ENG SUGGEST A LARGER RADIATOR, RETIMING OF THE IGNITION, AND/OR A RICHER MIXTURE MAY PRECLUDE RECURRENCE OF THE PROBLEM.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF

Phase of Operation: TAKEOFF - INITIAL CLIMB

#### **Findings**

1. (C) POWERPLANT - OVERTEMPERATURE

2. (C) ENGINE ASSEMBLY, PISTON - BURNED

3. (C) ACFT/EQUIP, INADEQUATE DESIGN - MANUFACTURER

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: MAIN GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### Findings

4. (F) TERRAIN CONDITION - ROUGH/UNEVEN

- 5. LANDING GEAR, NOSE GEAR OVERLOAD
- 6. LANDING GEAR, NOSE GEAR COLLAPSED

Page 2 of 5 DEN88DTE06

# **Factual Information**

#### **Pilot Information**

Certificate:	Commercial	Age:	39.Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 28, 1988
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1272 hours (Total, all aircraft), 20 hours (Total, this make and model), 1145 hours (Pilot In Command, all aircraft)		

## **Aircraft and Owner/Operator Information**

Aircraft Make:	HELFRICH-LEONARD	Registration:	N250TH
Model/Series:	BD-5B BD-5B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	1032
Landing Gear Type:	Retractable - Tricycle	Seats:	1
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	1100 lbs
Time Since Last Inspection:	10 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	311 Hrs	Engine Manufacturer:	HONDA
ELT:	Not installed	Engine Model/Series:	1250
Registered Owner:	MARK E. FOSTER	Rated Power:	70 Horsepower
Operator:	FOSTER MARK E.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 DEN88DTE06

## **Meteorological Information and Flight Plan**

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	APA	Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	20°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	26°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(APA)	Type of Flight Plan Filed:	None
Destination:	(APA)	Type of Clearance:	None
Departure Time:	12:25 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	CENTENNIAL APA	Runway Surface Type:	Asphalt
Airport Elevation:	5800 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	10000 ft / 100 ft	VFR Approach/Landing:	Forced landing

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.580581,-104.859794(est)

Page 4 of 5 DEN88DTE06

#### **Administrative Information**

Investigator In Charge (IIC):	Burton jr., Benjamin
Additional Participating Persons:	
Original Publish Date:	July 10, 1989
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=17330

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN88DTE06