



Aviation Investigation Final Report

Location: HARRISON, Arkansas Accident Number: DEN91LA001

Date & Time: October 1, 1990, 17:30 Local Registration: N4264D

Aircraft: Raven S-60A Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE STUDENT PILOT HAD BEEN FLYING HIS BALLOON FOR ABOUT AN HOUR WHEN HE ELECTED TO LAND. HE ATTEMPTED TO LAND IN AN ESTIMATED 15 KNOT WIND. HE SAID THAT WHEN THE BALLOON TOUCHED DOWN, THE WIND STARTED TO DRAG THE BALLOON TOWARD SOME ELECTRICAL POWER LINES. HE JUMPED OUT OF THE BASKET JUST PRIOR TO THE BALLOON STRIKING THE WIRES. THE BALLOON SUSTAINED SUBSTANTIAL DAMAGE TO THE ENVELOPE IN A POSTACCIDENT FIRE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE STUDENT PILOT'S IMPROPER INFLIGHT PLANNING AND INACCURATE EVALUATION OF THE SURFACE WEATHER. A FACTOR WAS THE UNFAVORABLE WIND.

Findings

Occurrence #1: IN FLIGHT ENCOUNTER WITH WEATHER

Phase of Operation: LANDING

Findings

1. (F) WEATHER CONDITION - UNFAVORABLE WIND

2. (C) IN-FLIGHT PLANNING/DECISION - IMPROPER - PILOT IN COMMAND

3. (C) WEATHER EVALUATION - INACCURATE - PILOT IN COMMAND

Page 2 of 5 DEN91LA001

Factual Information

Pilot Information

Certificate:	Student	Age:	25,Male
Airplane Rating(s):	None	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	5 hours (Total, all aircraft), 5 hours (Total, this make and model), 1 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

	_		
Aircraft Make:	Raven	Registration:	N4264D
Model/Series:	S-60A S-60A	Aircraft Category:	Balloon
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	S60A-292
Landing Gear Type:		Seats:	0
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1600 lbs
Time Since Last Inspection:	0 Hrs	Engines:	0 Unknown
Airframe Total Time:		Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:		Rated Power:	
Operator:	MIKE MILLS	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 DEN91LA001

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Thin Overcast / 25000 ft AGL	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	135°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:	(NONE)	Type of Clearance:	None
Departure Time:	16:40 Local	Type of Airspace:	

Airport Information

Airport:	NONE	Runway Surface Type:
Airport Elevation:		Runway Surface Condition:
Runway Used:	0	IFR Approach: None
Runway Length/Width:		VFR Approach/Landing: Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	On-ground
Ground Injuries:	N/A	Aircraft Explosion:	On-ground
Total Injuries:	1 None	Latitude, Longitude:	

Page 4 of 5 DEN91LA001

Administrative Information

Investigator In Charge (IIC):	Collins, Robert
Additional Participating Persons:	
Original Publish Date:	November 9, 1992
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=18044

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN91LA001