

Aviation Investigation Final Report

Location: ERIE, Colorado Accident Number: DEN91LA021

Date & Time: November 25, 1990, 16:50 Local Registration: N4557E

Aircraft: GULFSTREAM AA-5B Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PRIVATE PILOT WAS FLYING TWO PASSENGERS ON A ROUND TRIP CROSS COUNTRY FLIGHT. ACCORDING TO THE PILOT, HE HAD THE BRAKES REPAIRED AT EL PASO, TEXAS, AND WAS DISTRACTED BY WORRY OVER THE BRAKES ABILITY TO STOP ON THE DOWN HILL RUNWAY. HE REPORTED THAT HE MADE A NORMAL APPROACH TO RUNWAY 27, AND FLARED HIGH BECAUSE OF THE DARKNESS, RESULTING IN A HARD LANDING. THE PLANE BOUNCED BACK INTO THE AIR, THE PILOT ADDED POWER AND MADE A GO-AROUND. HE SAID THE ENGINE VIBRATED BADLY, AND HE ASSUMED THE PROPELLER STRUCK THE RUNWAY, EITHER DURING THE HARD LANDING OR AS HE ADDED POWER. ON THE SECOND APPROACH, AT TOUCHDOWN, THE NOSE GEAR COLLAPSED, THE PLANE DEPARTED THE RUNWAY, SHEARED THE MAIN GEAR AND CAME TO REST NOSE DOWN. THE RIGHT WING WAS BENT BACK, BOTH WING SPARS, THE FUSELAGE AND TAIL SECTION WERE DAMAGED. THE INVESTIGATION REVEALED THE MAIN LANDING GEAR LEGS WERE OVER STRESSED AND THE LOWER FUSELAGE WAS CRUSHED INWARD.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: IMPROPER FLARE BY THE PILOT, WHICH RESULTED IN A HARD LANDING. A REALTED FACTOR WAS: LOW LIGHT CONDITION AT DUSK.

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - ABORTED

Findings

1. (F) LIGHT CONDITION - DUSK

2. (C) FLARE - IMPROPER - PILOT IN COMMAND

Occurrence #2: NOSE GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

3. LANDING GEAR - OVERLOAD

Occurrence #3: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING

Occurrence #4: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING

Findings

4. TERRAIN CONDITION - SOFT

Page 2 of 5 DEN91LA021

Factual Information

Pilot Information

Certificate:	Private	Age:	26,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	May 22, 1990
Occupational Pilot:	UNK Last Flight Review or Equivalent:		
Flight Time:	85 hours (Total, all aircraft), 9 hours (Total, this make and model), 45 hours (Last 90 days, all aircraft), 60 hours (Last 30 days, all aircraft), 9 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	GULFSTREAM	Registration:	N4557E
Model/Series:	AA-5B AA-5B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	AA-5B-1230
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2400 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-360-A4K
Registered Owner:	DONALD S. MEINEN	Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 DEN91LA021

Meteorological Information and Flight Plan

Conditions at Accident Site: Visual (VMC) Condition of Light: Dusk Dusk Distance from Accident Site: Direction from Accident Site: Lowest Cloud Condition: Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 6 knots / Turbulence Type Forecast/Actual: Wind Direction: 240° Turbulence Severity Forecast/Actual: Altimeter Setting: No Obscuration; No Precipitation Departure Point: TRINIDAD , CO (TAD) Type of Flight Plan Filed: Visual (VMC) Destination: Departure Time: Direction Accident Site: Direction Accident Site: Direction From Accident Site: 15 miles / Combined / Procedent Site: Direction from Accident Site:				
Observation Time: Lowest Cloud Condition: Clear Visibility 15 miles Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 6 knots / Turbulence Type Forecast/Actual: Wind Direction: 240° Turbulence Severity Forecast/Actual: Altimeter Setting: Temperature/Dew Point: -18°C / -18°C Precipitation and Obscuration: No Obscuration; No Precipitation Departure Point: TRINIDAD , CO (TAD) Type of Flight Plan Filed: VFR Destination: Type of Clearance: None	Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dusk
Lowest Cloud Condition: Clear Visibility None Visibility (RVR): Wind Speed/Gusts: 6 knots / Turbulence Type Forecast/Actual: Wind Direction: 240° Turbulence Severity Forecast/Actual: Altimeter Setting: Temperature/Dew Point: Temperature/Dew Point: Temperature/Dew Point: Temperature/Dew Point: Temperature/Dew Point: Type of Flight Plan Filed: VFR Destination: Type of Clearance: None	Observation Facility, Elevation:		Distance from Accident Site:	
Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 6 knots / Turbulence Type Forecast/Actual: Wind Direction: 240° Turbulence Severity Forecast/Actual: Altimeter Setting: Temperature/Dew Point: -18°C / -18°C Precipitation and Obscuration: No Obscuration; No Precipitation Departure Point: TRINIDAD , CO (TAD) Type of Flight Plan Filed: VFR Destination: Type of Clearance: None	Observation Time:		Direction from Accident Site:	
Wind Speed/Gusts: 6 knots / Turbulence Type Forecast/Actual: Wind Direction: 240° Turbulence Severity Forecast/Actual: Altimeter Setting: Temperature/Dew Point: -18°C / -18°C Precipitation and Obscuration: No Obscuration; No Precipitation Departure Point: TRINIDAD , CO (TAD) Type of Flight Plan Filed: VFR Destination: Type of Clearance: None	Lowest Cloud Condition:	Clear	Visibility	15 miles
Wind Direction: 240° Turbulence Severity Forecast/Actual: Altimeter Setting: Temperature/Dew Point: -18°C / -18°C Precipitation and Obscuration: No Obscuration; No Precipitation Departure Point: TRINIDAD , CO (TAD) Type of Flight Plan Filed: VFR Destination: Type of Clearance: None	Lowest Ceiling:	None	Visibility (RVR):	
Altimeter Setting: Temperature/Dew Point: -18°C / -18°C Precipitation and Obscuration: No Obscuration; No Precipitation Departure Point: TRINIDAD , CO (TAD) Type of Flight Plan Filed: VFR Destination: Type of Clearance: None	Wind Speed/Gusts:	6 knots /	,,	/
Precipitation and Obscuration: No Obscuration; No Precipitation Departure Point: TRINIDAD , CO (TAD) Type of Flight Plan Filed: VFR Destination: Type of Clearance: None	Wind Direction:	240°		/
Departure Point: TRINIDAD , CO (TAD) Type of Flight Plan Filed: VFR Destination: Type of Clearance: None	Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Destination: Type of Clearance: None	Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
7,4-0.000	Departure Point:	TRINIDAD , CO (TAD)	Type of Flight Plan Filed:	VFR
Departure Time: 14:30 Local Type of Airspace:	Destination:		Type of Clearance:	None
	Departure Time:	14:30 Local	Type of Airspace:	

Airport Information

Airport:	TRI COUNTY 48V	Runway Surface Type:	Asphalt
Airport Elevation:	5151 ft msl	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	3800 ft / 60 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	40.020362,-105.0391(est)

Page 4 of 5 DEN91LA021

Administrative Information

Investigator In Charge (IIC): Collins, Robert

Additional Participating Persons:

Original Publish Date: February 12, 1993

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=18056

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN91LA021