



Aviation Investigation Final Report

Location: AVON, Colorado Accident Number: DEN91LA100

Date & Time: July 14, 1991, 08:15 Local Registration: N57053

Aircraft: Aerostar S57-A Aircraft Damage: Substantial

Defining Event: 3 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE BALLOON PILOT WAS LOOKING FOR A SUITABLE PLACE TO LAND. HIS ATTENTION WAS DIVERTED BY PERSONS ON THE GROUND AND RADIO COMMUNICATIONS WITH THE CHASE CREW. WHEN HE LOOKED UP, HE SAW POWERLINES DIRECTLY AHEAD. HE PULLED THE DEFLATION LINE AND TOLD HIS PASSENGERS TO GET TO THE BOTTOM OF THE BASKET. THE BALLOON CONTACTED THE POWERLINES, IGNITING SKIRT PANELS AND DRIPPING MELTED FABRIC ON THE OCCUPANTS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN A VISUAL LOOKOUT. A FACTOR WAS: THE PILOT'S ATTENTION BEING DIVERTED.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: APPROACH

Findings

- 1. (C) VISUAL LOOKOUT NOT MAINTAINED PILOT IN COMMAND
- 2. (F) DIVERTED ATTENTION PILOT IN COMMAND
- 3. CLEARANCE INADEQUATE
- 4. OBJECT WIRE, TRANSMISSION

Page 2 of 5 DEN91LA100

Factual Information

Pilot Information

Certificate:	Commercial	Age:	45.Male
Airplane Rating(s):	None	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Balloon	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	None None	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	429 hours (Total, all aircraft), 214 hours (Total, this make and model), 421 hours (Pilot In Command, all aircraft), 15 hours (Last 90 days, all aircraft), 14 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Aerostar	Registration:	N57053
Model/Series:	S57-A S57-A	Aircraft Category:	Balloon
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	SS73052
Landing Gear Type:		Seats:	0
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	0 Hrs	Engines:	0 Unknown
Airframe Total Time:		Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	ROLAND L. & RUTH B. ELKINS	Rated Power:	
Operator:	ROLAND L. & RUTH B. ELKINS	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 DEN91LA100

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	40 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	13°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	AVON , CO	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	07:50 Local	Type of Airspace:	

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	2 Minor	Aircraft Fire:	In-flight
Ground Injuries:	N/A	Aircraft Explosion:	In-flight
Total Injuries:	3 Minor	Latitude, Longitude:	

Page 4 of 5 DEN91LA100

Administrative Information

Investigator In Charge (IIC): Scott, Arnold

Additional Participating Persons:

Original Publish Date: May 5, 1993

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=18112

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 DEN91LA100