



# **Aviation Investigation Final Report**

Location: FORT WORTH, Texas Accident Number: FTW92FA107

Date & Time: April 8, 1992, 22:00 Local Registration: N67816

Aircraft: CESSNA 150 II Aircraft Damage: Substantial

**Defining Event:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

DURING A NIGHT VFR SOLO CROSS-COUNTRY FLIGHT THE STUDENT PILOT BECAME DISORIENTED AND LANDED AT AN ALTERNATE ENROUTE AIRPORT. HE SUBSEQUENTLY DEPARTED WITHOUT REFUELING AND AGAIN BECAME DISORIENTED AND WAS UNABLE TO FIND HIS FINAL DESTINATION AIRPORT. HE FOUND A KNOWN REFERENCE AND WAS ATTEMPTING TO FLY TO HIS DESTINATION WHEN THE ENGINE BEGAN TO LOSE POWER. AT THAT POINT THE PILOT TURNED TOWARDS ALLIANCE AIRPORT WHEN TOTAL POWER LOSS OCCURRED. DURING THE FORCED LANDING EMERGENCY DESCENT THE AIRPLANE STRUCK A TRANSMISSION LINE AND A TREE BEFORE AN UNCONTROLLED IMPACT WITH THE TERRAIN. ONE HALF PINT OF FUEL WAS FOUND IN THE FUEL TANKS AT THE ACCIDENT SITE.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A FUEL EXHAUSTION INDUCED ENGINE POWER LOSS DUE TO THE PILOT'S FAILURE TO REFUEL. A FACTOR WAS THE PILOT'S INADVERTENT DISORIENTATION.

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: APPROACH - VFR PATTERN - BASE LEG/BASE TO FINAL

**Findings** 

1. (F) BECAME LOST/DISORIENTED - INADVERTENT - PILOT IN COMMAND

2. (C) FLUID, FUEL - EXHAUSTION

3. (C) REFUELING - NOT PERFORMED - PILOT IN COMMAND

------

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: DESCENT - EMERGENCY

Findings

4. OBJECT - WIRE, TRANSMISSION

5. OBJECT - TREE(S)

-----

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Page 2 of 5 FTW92FA107

# **Factual Information**

#### **Pilot Information**

Certificate:	Student	Age:	21,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	February 21, 1992
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	30 hours (Total, all aircraft), 30 hours (Total, this make and model)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	CESSNA	Registration:	N67816
Model/Series:	150 II 150 II	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	15282034
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	February 23, 1991 100 hour	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	62 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	6586 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	0-235-L2C
Registered Owner:	HODGE, ANTHONY W.	Rated Power:	110 Horsepower
Operator:	HODGE, ANTHONY W.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 FTW92FA107

# Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Night/bright
	Distance from Accident Site:	
	Direction from Accident Site:	
Clear	Visibility	15 miles
Broken / 10000 ft AGL	Visibility (RVR):	
10 knots /	Turbulence Type Forecast/Actual:	/
180°	Turbulence Severity Forecast/Actual:	/
29 inches Hg	Temperature/Dew Point:	27°C
No Obscuration; No Precipita	ation	
WICHITA FALLS (T47)	Type of Flight Plan Filed:	VFR
	Type of Clearance:	None
21:30 Local	Type of Airspace:	Class D;Class E
	Clear Broken / 10000 ft AGL 10 knots /  180°  29 inches Hg No Obscuration; No Precipita WICHITA FALLS (T47)	Distance from Accident Site: Direction from Accident Site: Visibility  Broken / 10000 ft AGL Visibility (RVR):  10 knots / Turbulence Type Forecast/Actual:  180° Turbulence Severity Forecast/Actual:  29 inches Hg Temperature/Dew Point: No Obscuration; No Precipitation WICHITA FALLS (T47) Type of Flight Plan Filed: Type of Clearance:

# **Airport Information**

Airport:	FORT WORTH ALLIANCE AFW	Runway Surface Type:	Asphalt
Airport Elevation:	722 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	34	IFR Approach:	
Runway Length/Width:	9600 ft / 150 ft	VFR Approach/Landing:	Forced landing

# Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	

Page 4 of 5 FTW92FA107

#### **Administrative Information**

Investigator In Charge (IIC): Smith, Joyce

Additional Participating Persons:

Original Publish Date: June 11, 1993

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=18356

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 FTW92FA107