

Aviation Investigation Final Report

Location:	ROSWELL, New Me	exico	Accident Number:	FTW92LA234
Date & Time:	September 30, 199	2, 14:57 Local	Registration:	N2372V
Aircraft:	PIPER	PA-38-112	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 Minor
Flight Conducted Under:	Part 91: General aviation - Instructional			

Analysis

A STUDENT PILOT ON A SOLO CROSS COUNTRY FLIGHT STALLED THE AIRPLANE ON FINAL APPROACH. THE AIRPLANE IMPACTED THE GROUND IN A NOSE DOWN ATTITUDE IN A SLIGHT RIGHT TURN.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT FAILED TO MAINTAIN THE CORRECT AIRSPEED ON FINAL APPROACH AND ALLOWED THE AIRCRAFT TO STALL.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings
1. (C) STALL - INADVERTENT - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: DESCENT - UNCONTROLLED

Factual Information

Pilot Information

T not information			
Certificate:	Student	Age:	39,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 30, 1992
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	48 hours (Total, all aircraft), 40 hours (Total, this make and model), 30 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

		Devictuation	N0070V
Aircraft Make:	PIPER	Registration:	N2372V
Model/Series:	PA-38-112 PA-38-112	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	38-82A00029
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	September 3, 1992 100 hour	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	30 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2238 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-235-L2A
Registered Owner:	SOUTHWEST AVIATION INC.	Rated Power:	112 Horsepower
Operator:	SOUTHWEST AVIATION INC.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	GRWS

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ROW ,3669 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	14:06 Local	Direction from Accident Site:	350°
Lowest Cloud Condition:	Clear	Visibility	60 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	170°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	31°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	LAS CRUCES , NM (LRU)	Type of Flight Plan Filed:	VFR
Destination:	(ROW)	Type of Clearance:	VFR
Departure Time:	12:20 Local	Type of Airspace:	Class D;Class E

Airport Information

Airport:	ROSWELL AIR CENTER ROW	Runway Surface Type:	Asphalt
Airport Elevation:	3669 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	
Runway Length/Width:	10000 ft / 200 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	33.640377,-104.380653(est)

Administrative Information

Investigator In Charge (IIC):	Casanova, Hector		
Additional Participating Persons:	JOHN C SANDERS; ALBUQUERQUE , NM		
Original Publish Date:	June 30, 1993		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=18572		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.