



Aviation Investigation Final Report

Location: CLEVELAND, Texas Accident Number: FTW93LA009

Date & Time: October 6, 1992, 14:10 Local Registration: N6554E

Aircraft: CESSNA 175 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

DURING A TAKEOFF FROM A PRIVATE AIRFIELD THE AIRPLANE LOST ENGINE POWER IN THE INITIAL CLIMB. THE PILOT ATTEMPTED TO RETURN TO THE AIRFIELD BY CONDUCTING A 180 DEGREE TURN, HOWEVER, HE HAD INSUFFICIENT ALTITUDE TO CLEAR OBSTACLES IN HIS PATH, SO HE ELECTED TO LAND IN THE ONLY AVAILABLE AREA, WHICH WAS UNSUITABLE. AN EXAMINATION OF THE ENGINE FAILED TO REVEAL A CAUSE FOR THE LOSS OF POWER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE LOSS OF ENGINE POWER FOR UNDETERMINED REASONS. A FACTOR WAS THE UNSUITABLE TERRAIN.

Findings

Occurrence #1: LOSS OF ENGINE POWER
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings

2. (F) TERRAIN CONDITION - NONE SUITABLE

- 3. OBJECT FENCE
- 4. OBJECT TREE(S)

Page 2 of 5 FTW93LA009

Factual Information

Pilot Information

Certificate:	Private	Age:	26.Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 1, 1992
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	179 hours (Total, all aircraft), 8 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N6554E
Model/Series:	175 175	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	56054
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	January 2, 2000 Annual	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	GO-300-A
Registered Owner:	FERSCHLER, DONALD	Rated Power:	175 Horsepower
Operator:	FERSCHLER, DONALD	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 FTW93LA009

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	7 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	27°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	(NONE)	Type of Flight Plan Filed:	None
Destination:	LIBERTY , TX (T78)	Type of Clearance:	None
Departure Time:	14:10 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	30.340454,-95.069053(est)

Page 4 of 5 FTW93LA009

Administrative Information

Investigator In Charge (IIC): Ellis, Matthew

Additional Participating Persons:

Original Publish Date: May 26, 1993

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=18594

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 FTW93LA009