



Aviation Investigation Final Report

Location: RUSTON, Louisiana Accident Number: FTW93LA084

Date & Time: February 11, 1993, 16:50 Local Registration: N6290Y

Aircraft: PIPER PA-23-250 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

WHILE LANDING ON A RUNWAY WITH A DISPLACE THRESHOLD, BRAKING ACTION WAS LOST AND THE PILOT WAS UNABLE TO STOP THE AIRPLANE ON THE REMAINING RUNWAY. SUBSEQUENTLY, THE AIRPLANE RAN OFF THE END OF THE RUNWAY AND COLLIDED WITH THREE SMALL TREES, WHICH DAMAGED THE RIGHT WING. AN INSPECTION REVEALED A LEAK IN A BRAKE LINE FITTING HAD ALLOWED THE HYDRAULIC SYSTEM TO BE DEPLETED OF FLUID.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FAILURE AT A HYDRAULIC FITTING, WHICH RESULTED IN A HYDRAULIC LEAK, LOSS OF HYDRAULIC FLUID, AND SUBSEQUENT LOSS OF BRAKING ACTION DURING THE LANDING ROLL.

Findings

Occurrence #1: OVERRUN

Phase of Operation: LANDING - ROLL

Findings

- 1. AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION DISPLACED THRESHOLD
- 2. (C) HYDRAULIC SYSTEM, FITTING FAILURE, TOTAL
- 3. (C) FLUID, HYDRAULIC LEAK
- 4. (C) LANDING GEAR, NORMAL BRAKE SYSTEM INOPERATIVE

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: LANDING - ROLL

Findings 5. OBJECT - TREE(S)

Page 2 of 6 FTW93LA084

Factual Information

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	23,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	January 25, 1993
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	698 hours (Total, all aircraft), 42 hours (Total, this make and model), 570 hours (Pilot In Command, all aircraft), 86 hours (Last 90 days, all aircraft), 57 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

Page 3 of 6 FTW93LA084

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N6290Y
Model/Series:	PA-23-250 PA-23-250	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	27-3450
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	July 14, 1992 Annual	Certified Max Gross Wt.:	5200 lbs
Time Since Last Inspection:	89 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	3700 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-540-C4B5
Registered Owner:	MOUNTAIN AVIATION	Rated Power:	250 Horsepower
Operator:	MOUNTAIN AVIATION	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

onditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
oservation Facility, Elevation:	MLU ,79 ft msl	Distance from Accident Site:	30 Nautical Miles
oservation Time:	16:49 Local	Direction from Accident Site:	90°
west Cloud Condition:	Scattered / 5000 ft AGL	Visibility	8 miles
owest Ceiling:	None	Visibility (RVR):	
ind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
ind Direction:	230°	Turbulence Severity Forecast/Actual:	/
timeter Setting:	29 inches Hg	Temperature/Dew Point:	19°C / 12°C
ecipitation and Obscuration:	No Obscuration; No Precipitation		
eparture Point:	BATON ROUGE , LA (BTR)	Type of Flight Plan Filed:	IFR
estination:	(RSN)	Type of Clearance:	None
eparture Time:	15:45 Local	Type of Airspace:	Class G
ind Direction: timeter Setting: recipitation and Obscuration: reparture Point:	230° 29 inches Hg No Obscuration; No Precipital BATON ROUGE , LA (BTR) (RSN)	Forecast/Actual: Turbulence Severity Forecast/Actual: Temperature/Dew Point: ation Type of Flight Plan Filed: Type of Clearance:	IFR None

Page 4 of 6 FTW93LA084

Airport Information

Airport:	RUSTON MUNICIPAL RSN	Runway Surface Type:	Asphalt
Airport Elevation:	327 ft msl	Runway Surface Condition:	Dry
Runway Used:	16	IFR Approach:	
Runway Length/Width:	2798 ft / 90 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 5 of 6 FTW93LA084

Administrative Information

Investigator In Charge (IIC):	Ellis, Matthew	
Additional Participating Persons:	ANTHONY MICHELLI; BATON ROUGE , LA	
Original Publish Date:	May 28, 1993	
Last Revision Date:		
Investigation Class:	Class	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=18637	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 FTW93LA084