



# Aviation Investigation Final Report

<b>Location:</b>	OSAGE, Arkansas	<b>Accident Number:</b>	FTW94LA144
<b>Date &amp; Time:</b>	May 4, 1994, 18:30 Local	<b>Registration:</b>	N90469
<b>Aircraft:</b>	HILLER UH-12E	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 Minor
<b>Flight Conducted Under:</b>	Part 137: Agricultural		

## Analysis

ACCORDING TO THE PILOT, THE HELICOPTER WAS SERVICED WITH 30 GALLONS OF FUEL FOR AN AERIAL APPLICATION FLIGHT TO DISPENSE 100 GALLONS OF PESTICIDES. AFTER A 45 MINUTE SORTIE, THE HELICOPTER WAS EN ROUTE BACK TO THE LOADING SITE, OVER HEAVILY WOODED MOUNTAINOUS TERRAIN, WHEN THE PILOT EXPERIENCED A LOSS OF ENGINE POWER. THE ENGINE REGAINED POWER TEMPORARILY, AND LOST POWER FOR A SECOND TIME 5 TO 8 SECONDS LATER. THE PILOT AUTOROTATED ABOVE THE TREE TOPS AND SETTLED THROUGH THE TREES COMING TO REST IN AN UPRIGHT POSITION. THERE WAS NO EVIDENCE OF A FUEL SPILL AND NO FUEL WAS FOUND IN THE FUEL CELL. THE AVERAGE FUEL BURN RATE IS 25 TO 26 GALLONS PER HOUR. THE ENGINE WAS SUCCESSFULLY RUN IN AN ENGINE TEST CELL.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FUEL EXHAUSTION DUE TO THE PILOT'S FAILURE TO REFUEL AND THE LACK OF SUITABLE TERRAIN FOR A FORCED LANDING.

## Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL  
Phase of Operation: CRUISE - NORMAL

Findings

1. (F) FLUID,FUEL - EXHAUSTION
2. (C) REFUELING - NOT PERFORMED - PILOT IN COMMAND

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - EMERGENCY

Findings

3. TERRAIN CONDITION - MOUNTAINOUS/HILLY
4. (C) TERRAIN CONDITION - NONE SUITABLE

## Factual Information

On May 4, 1994, at 1830 central daylight time, a Hiller UH-12E helicopter, N90469, was substantially damaged following a loss of engine power near Osage, Arkansas. The airline transport rated pilot sustained minor injuries. Visual meteorological conditions prevailed for the aerial application flight.

According to the operator, the turbine powered helicopter was supporting a gypsy moth eradication program within the Ozark National Forest. The pilot stated that the helicopter was serviced with 100 gallons pesticides and 30 gallons of Jet A fuel for the ninth sortie of the day.

Approximately 45 minutes later, while en route back to the load site, the engine lost power. The pilot stated that he entered autorotation, and the engine auto reignite restarted the engine. The pilot added that he turned towards an open field to make a precautionary landing, and approximately 5 to 8 seconds later, the engine lost power for the second time.

The pilot reentered an autorotation to the heavily wooded area ahead and was able stop all forward motion above the tree tops, settling through the trees. After falling 40 to 50 feet, the helicopter came to rest in the upright position lodged between the tree trunks.

According to the operator, the fuel cell and the fuel lines were not compromised during the crash sequence. No fuel was found in the fuel cell, and there was no evidence of a fuel spill on the ground. According to the engine manufacturer, the average fuel burn rate is 25 to 26 gallons per hour. A successful engine run was accomplished in a test cell, and no anomalies were found with either the fuel control or associated fuel system components.

## Pilot Information

<b>Certificate:</b>	Airline transport	<b>Age:</b>	46, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane; Helicopter	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical-w/ waivers/lim	<b>Last FAA Medical Exam:</b>	April 15, 1994
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	10146 hours (Total, all aircraft), 210 hours (Total, this make and model), 9086 hours (Pilot In Command, all aircraft), 12 hours (Last 90 days, all aircraft), 11 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	HILLER	<b>Registration:</b>	N90469
<b>Model/Series:</b>	UH-12E UH-12E	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Restricted (Special)	<b>Serial Number:</b>	2358
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	3
<b>Date/Type of Last Inspection:</b>	April 13, 1994 100 hour	<b>Certified Max Gross Wt.:</b>	3100 lbs
<b>Time Since Last Inspection:</b>	10 Hrs	<b>Engines:</b>	1 Turbo shaft
<b>Airframe Total Time:</b>	5989 Hrs	<b>Engine Manufacturer:</b>	ALLISON
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	250-C20B
<b>Registered Owner:</b>	EVERGREEN EQUITY INC	<b>Rated Power:</b>	420 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	
<b>Operator Does Business As:</b>	EVERGREEN HELICOPTERS INC.	<b>Operator Designator Code:</b>	LCFG

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	HRO ,1364 ft msl	<b>Distance from Accident Site:</b>	13 Nautical Miles
<b>Observation Time:</b>	11:51 Local	<b>Direction from Accident Site:</b>	65°
<b>Lowest Cloud Condition:</b>	Scattered / 5000 ft AGL	<b>Visibility</b>	15 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	10 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	350°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30 inches Hg	<b>Temperature/Dew Point:</b>	22°C / 8°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>		<b>Type of Flight Plan Filed:</b>	Company VFR
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	17:45 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>		<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>		<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>	0	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Minor	<b>Latitude, Longitude:</b>	36.29079,-93.290176(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Wigington, Douglas
<b>Additional Participating Persons:</b>	DAVID F HALL; LITTLE ROCK , AR
<b>Original Publish Date:</b>	November 14, 1994
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=19047">https://data.nts.gov/Docket?ProjectID=19047</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).