



# Aviation Investigation Final Report

---

<b>Location:</b>	Scott City, Kansas	<b>Accident Number:</b>	CEN23LA264
<b>Date &amp; Time:</b>	June 24, 2023, 11:30 Local	<b>Registration:</b>	N9721Q
<b>Aircraft:</b>	Beech B19	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Fuel starvation	<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

---

## Analysis

The pilot stated that after he started the engine, he let it idle about 600 rpm for a “few minutes,” and began to taxi to the runway for departure. He waited for another airplane to perform a back-taxi and depart, then he back-taxed and completed an engine run-up before realizing he left something behind. He then taxied back to the fixed base operator (FBO), collected his items, and again taxied to the runway for departure. He did not complete another engine run-up before takeoff.

During the takeoff roll, he noticed the engine rpm increased and did not note any anomalies. During the initial climb, the engine rpm maintained about 2,200 rpm with full throttle set. He stated that he was able to climb about 500 ft above ground level (agl) and attempted a return to the airport. He said that when he was abeam the runway, he thought he was “losing altitude and power,” and made a shallow left turn towards the runway. Unable to maintain altitude during the turn, the pilot landed on a dirt road. During touchdown, the airplane bounced, exited the roadway, impacted a ditch, and slid into a cornfield, which resulted in substantial damage to the fuselage.

During a postaccident examination, no preimpact mechanical malfunctions or failures were discovered that would have precluded normal operation.

When the temperature and dewpoint at the time of the accident were plotted on a carburetor icing probability chart, it was revealed that the airplane was operating in an environment conducive for serious carburetor icing at a glide power setting. The pilot stated that he checked the carburetor heat before departure. After the carburetor heat check, it is likely that ice began to form in the carburetor’s venturi during the extended ground operation before departure, which, in turn, limited the engine rpm at 2,200.

# Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A partial loss of engine power as a result of carburetor icing that formed while the engine was operating at a low power setting for an extended period before departure.

## Findings

<b>Environmental issues</b>	Conducive to carburetor icing - Effect on equipment
<b>Aircraft</b>	Intake anti-ice, deice - Not used/operated

## Factual Information

### History of Flight

Initial climb	Fuel starvation (Defining event)
Initial climb	Loss of engine power (partial)

On June 24, 2023, about 1130 central daylight time, a Beech B19, N9721Q, sustained substantial damage when it was involved in an accident near Scott City, Kansas. The pilot was uninjured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

According to the pilot, he added 17.16 gallons of fuel which brought the total quantity to about 30 gallons. He then started the engine, let it idle about 600 rpm for a “few minutes,” and began to taxi to runway 35 at Scott City Municipal Airport (TQK). He waited for another airplane to perform a back-taxi and depart, then he back-taxed and completed an engine run-up before realizing he left something behind. He then taxied back to the FBO, collected his items, and taxied back to the runway for departure.

The pilot stated that during the takeoff roll, he noticed that the engine rpm increased and did not note any anomalies. During the initial climb, he saw the engine RPM maintained about 2,200 rpm with full throttle. He stated that he was able to climb to about 500 ft agl and attempted a return to the airport. He said that when he was abeam the runway, he thought he was “losing altitude and power,” and made a shallow left turn towards the runway. Unable to maintain altitude during the turn, the pilot attempted a landing on a dirt road. During touchdown, the airplane bounced, exited the roadway, impacted a ditch, and slid into a cornfield, which resulted in substantial damage to the fuselage.

A pilot witness reported seeing the accident airplane depart and noted that it did not appear to be climbing well when it started a turn to the northeast. He estimated the airplane was about 50 to 100 ft agl, when he lost sight of it while he was taxiing. After he turned his airplane around, he saw the accident airplane again when it was southwest of the runway. He stated that it appeared to be less than 100 ft agl and about 30° nose down at the time of impact.

During a postaccident examination, continuity was established from the engine controls in the cockpit to their respective engine attach points. No preimpact mechanical malfunctions or anomalies were found that would have precluded normal operation.

The reported weather conditions about 15 minutes before the accident included a temperature of 82°F and dewpoint of 59°F. When plotted on a carburetor icing probability chart, the airplane was operating in an environment conducive for serious carburetor icing at a glide power setting. (See Figure 1)




Figure 1: Carburetor Icing Probability Chart. Reference: Special Airworthiness Information Bulletin CE-09-35

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	50
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Lap only
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 3 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	January 25, 2023
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	May 5, 2018
<b>Flight Time:</b>	134 hours (Total, all aircraft), 84 hours (Total, this make and model), 116 hours (Pilot In Command, all aircraft), 0 hours (Last 90 days, all aircraft), 0 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Beech	<b>Registration:</b>	N9721Q
<b>Model/Series:</b>	B19	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1970	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	MB-493
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	January 10, 2023 Annual	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>	4 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	3482 Hrs as of last inspection	<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>	C91 installed, activated	<b>Engine Model/Series:</b>	O-320-E2C
<b>Registered Owner:</b>	On file	<b>Rated Power:</b>	150 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KTQK, 2963 ft msl	<b>Distance from Accident Site:</b>	1 Nautical Miles
<b>Observation Time:</b>	11:15 Local	<b>Direction from Accident Site:</b>	176°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility:</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	12 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	20°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.96 inches Hg	<b>Temperature/Dew Point:</b>	28°C / 15°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	SCOTT CITY, KS (KTQK)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	CLAY CENTER, KS (KCYW)	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	09:15 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	SCOTT CITY MUNI TQK	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>	2968 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	38.484405,-100.88589(est)

## Preventing Similar Accidents

### Preventing Carburetor Icing (SA-029)

#### The Problem

According to NTSB aircraft accident data, from 2000 to 2011, carburetor icing was a cause or factor in about 250 accidents. On average, carburetor icing causes or contributes to two fatal accidents per year. Accident evidence shows that some pilots do not recognize weather conditions favorable to carburetor icing and inaccurately believe that carburetor icing is only a cold- or wet-weather problem. Pilots may also have not used the carburetor heat according to the aircraft's approved procedures to prevent carburetor ice formation. In addition, some pilots may not recognize and promptly act upon the signs of carburetor icing.

#### What can you do?

- Check the temperature and dew point for your flight to determine whether the conditions are favorable for carburetor icing. Remember, serious carburetor icing can occur in ambient temperatures as high as 90° F or in relative humidity conditions as low as 35 percent at glide power.
- Refer to your approved aircraft flight manual or operating handbook to ensure that you are using carburetor heat according to the approved procedures and properly perform the following actions:
  - Check the functionality of the carburetor heat before your flight.
  - Use carburetor heat to prevent the formation of carburetor ice when operating in conditions and at power settings in which carburetor icing is probable. Remember, ground idling or taxiing time can allow carburetor ice to accumulate before takeoff.
  - Immediately apply carburetor heat at the first sign of carburetor icing, which typically includes a drop in rpm or manifold pressure (depending upon how your airplane is equipped). Engine roughness may follow.
- Consider installing a carburetor temperature gauge, if available.
- Remember that aircraft engines that run on automotive gas may be more susceptible to carburetor icing than engines that run on Avgas.

See <https://www.nts.gov/Advocacy/safety-alerts/Documents/SA-029.pdf> for additional resources.

The NTSB presents this information to prevent recurrence of similar accidents. Note that this should not be considered guidance from the regulator, nor does this supersede existing FAA Regulations (FARs).

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Williams, David
<b>Additional Participating Persons:</b>	David Gobble; FAA
<b>Original Publish Date:</b>	October 5, 2023
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class 3</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=192456">https://data.ntsb.gov/Docket?ProjectID=192456</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).