

Aviation Investigation Final Report

Location: Metaline Falls, Washington **Accident Number:** WPR23LA273

Date & Time: July 1, 2023, 12:30 Local Registration: N68TP

Aircraft: Vans RV8 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel equipped airplane reported that during the landing rollout, after the tail came down, he felt and heard a "bang" as the airplane rolled over a concrete ring, embedded in the turf runway. The airplane continued down the runway and the right main landing gear tire dug into the ground, followed by the collapse of the right main landing gear. The fuselage sustained substantial damage. After exiting the airplane, the pilot noticed that the tailwheel steering link was broken. The pilot reported that there were no preaccident mechanical malfunctions or failures that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of directional control during landing due to impact with a concrete ring embedded in the grass runway.

Findings

Personnel issues Aircraft control - Pilot

Environmental issues (general) - Effect on equipment

Aircraft Directional control - Attain/maintain not possible

Page 2 of 6 WPR23LA273

Factual Information

History of Flight

Landing-landing roll	Miscellaneous/other
Landing-landing roll	Loss of control on ground (Defining event)
Landing-landing roll	Landing gear collapse

Pilot Information

Certificate:	Private	Age:	54,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	BasicMed Without waivers/limitations	Last FAA Medical Exam:	February 13, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 12, 2022
Flight Time:	4133 hours (Total, all aircraft), 1215 hours (Total, this make and model), 3994 hours (Pilot In Command, all aircraft), 56 hours (Last 90 days, all aircraft), 19 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 WPR23LA273

Aircraft and Owner/Operator Information

Aircraft Make:	Vans	Registration:	N68TP
Model/Series:	RV8	Aircraft Category:	Airplane
Year of Manufacture:	2015	Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	83300
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	June 1, 2023 Condition	Certified Max Gross Wt.:	1850 lbs
Time Since Last Inspection:	15 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1190.9 Hrs as of last inspection	Engine Manufacturer:	Superior
ELT:	C91A installed, not activated	Engine Model/Series:	XP IO-360-B1HD2
Registered Owner:	On file	Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	K63S,1886 ft msl	Distance from Accident Site:	30 Nautical Miles
Observation Time:	12:35 Local	Direction from Accident Site:	233°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/ None
Wind Direction:		Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.96 inches Hg	Temperature/Dew Point:	28°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Republic, WA (R49)	Type of Flight Plan Filed:	None
Destination:	Metaline Falls, WA	Type of Clearance:	None
Departure Time:	11:15 Local	Type of Airspace:	Class G

Page 4 of 6 WPR23LA273

Airport Information

Airport:	Sullivan Lake State 09S	Runway Surface Type:	Concrete;Grass/turf;Gravel
Airport Elevation:	2614 ft msl	Runway Surface Condition:	Dry
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	1765 ft / 100 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	48.85,-117.28

Page 5 of 6 WPR23LA273

Administrative Information

Investigator In Charge (IIC):	Blocher, Kristyn
Additional Participating Persons:	Taha Rabbani; Federal Aviation Administration; Spokane, WA
Original Publish Date:	November 2, 2023
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=192641

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 WPR23LA273