



# Aviation Investigation Final Report

<b>Location:</b>	Farmington, California	<b>Accident Number:</b>	WPR24LA114
<b>Date &amp; Time:</b>	March 16, 2024, 13:20 Local	<b>Registration:</b>	N38RK
<b>Aircraft:</b>	MOONEY AIRCRAFT CORP. M20K	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Fuel exhaustion	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The pilot reported that he intended to service the airplane with fuel at the destination airport, which had cheaper fuel and was a short distance away. During the preflight inspection he observed that the low fuel indicator was illuminated for one tank, and the panel gauge for the other indicated it was  $\frac{1}{4}$  full, which he estimated would equate to about 20 about gallons. He cross-checked the levels with the airplanes fuel totalizer system, which indicated 20 gallons of fuel remained.

While enroute, the pilot noticed the fuel gauge level dropping faster than he anticipated, and a short time later the engine lost all power due to fuel exhaustion. The pilot performed a forced landing onto a dirt road in farmland, after maneuvering the airplane under a power line. The airplane struck fence on roll-out and sustained substantial damage to both wings. The pilot and passenger were not injured.

The pilot reported there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation. The airplanes low fuel indicators illuminate when about  $2\frac{1}{2}$  gallons of fuel remain in their respective tanks. Each tank holds about 9 gallons of fuel when  $\frac{1}{4}$  full, rather than the 20 gallons the pilot had estimated. The pilot stated that he had mistakenly used the airplanes total fuel capacity of about 76 gallons when making that calculation, rather than half the value that a single tank could hold. He also stated that he may not have properly adjusted the totalizer the last time he serviced the airplane with fuel, hence its reading was not accurate. He stated that because the totalizer and fuel tank gauge readings were similar, due to confirmation bias he concluded that sufficient fuel remained.

The pilot stated that he is risk averse, and conservative in nature and has never departed with the low fuel light on before but, he surmised, the cheaper fuel at the destination likely influenced his decision to proceed with the flight.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper preflight fuel planning that resulted in the loss of engine power due to fuel exhaustion.

### Findings

Personnel issues	Preflight inspection - Pilot
Personnel issues	Fuel planning - Pilot
Personnel issues	Decision making/judgment - Pilot
Aircraft	Fuel - Fluid level

## Factual Information

### History of Flight

Enroute	Fuel exhaustion (Defining event)
Enroute	Off-field or emergency landing
Landing-landing roll	Collision with terr/obj (non-CFIT)

### Pilot Information

Certificate:	Private	Age:	58,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	July 2, 2023
Occupational Pilot:	No	Last Flight Review or Equivalent:	July 10, 2022
Flight Time:	825.3 hours (Total, all aircraft), 383.7 hours (Total, this make and model)		

### Aircraft and Owner/Operator Information

Aircraft Make:	MOONEY AIRCRAFT CORP.	Registration:	N38RK
Model/Series:	M20K	Aircraft Category:	Airplane
Year of Manufacture:	1986	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	25-1059
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	November 1, 2023 Annual	Certified Max Gross Wt.:	2900 lbs
Time Since Last Inspection:	10 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3378 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	TSIO-360-MB
Registered Owner:	On file	Rated Power:	210 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KSCK,33 ft msl	<b>Distance from Accident Site:</b>	14 Nautical Miles
<b>Observation Time:</b>	12:55 Local	<b>Direction from Accident Site:</b>	271°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	None / None
<b>Wind Direction:</b>		<b>Turbulence Severity Forecast/Actual:</b>	N/A / N/A
<b>Altimeter Setting:</b>	29.99 inches Hg	<b>Temperature/Dew Point:</b>	21°C / 2°C
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	Auburn, CA (AUN)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Oakdale, CA (O27)	<b>Type of Clearance:</b>	VFR;VFR flight following
<b>Departure Time:</b>	13:06 Local	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	Field NONE	<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>		<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>		<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	37.885117,-120.93498(est)

## Administrative Information

Investigator In Charge (IIC):	Simpson, Elliott
Additional Participating Persons:	Michael R McMillen; FAA FSDO; Oakland, CA
Original Publish Date:	October 24, 2024
Last Revision Date:	
Investigation Class:	<a href="#">Class 4</a>
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	<a href="https://data.nts.gov/Docket?ProjectID=193957">https://data.nts.gov/Docket?ProjectID=193957</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).