



# **Aviation Investigation Final Report**

Location: MALVERN, Arkansas Accident Number: FTW95LA210

Date & Time: May 20, 1995, 20:00 Local Registration: N7152M

Aircraft: CESSNA 175 Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

ACCORDING TO THE 94 HOUR PRIVATE PILOT, THE BRAKES FAILED DURING THE LANDING ROLL. THE AIRPLANE EXITED THE LEFT SIDE OF THE RUNWAY, TRAVELED ACROSS A ROAD AND IMPACTED A FENCE POST AND A TREE. EXAMINATION OF THE BRAKE SYSTEM REVEALED NO ANOMALIES AND SKID MARKS WERE FOUND ON THE RUNWAY. THE PILOT'S MOST RECENT FLIGHT WAS ON OCTOBER 2, 1994, 230 DAYS BEFORE THE ACCIDENT.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN DIRECTIONAL CONTROL. A FACTOR WAS THE PILOT'S LACK OF RECENT EXPERIENCE.

### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

#### **Findings**

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

2. (F) LACK OF RECENT EXPERIENCE - PILOT IN COMMAND

-----

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings
3. OBJECT - FENCE POST
4. OBJECT - TREE(S)

Page 2 of 6 FTW95LA210

#### **Factual Information**

On May 20, 1995, at 2000 central daylight time, a Cessna 175, N7152M, collided with a fence while landing near Malvern, Arkansas. The private pilot was not injured and the airplane sustained substantial damage. The airplane was being operated by Malvern Flyers, Inc., under Title 14 CFR Part 91. No flight plan was filed and visual meteorological conditions with calm winds prevailed for the local personal flight which departed Malvern at 1930 CDT.

According to the pilot, after landing on the first third of runway 03 at Malvern Municipal Airport, the airplane's brakes failed. The airplane exited the left side of the runway, passing through a ditch, across a road, and coming to rest against a tree and a fence post. Damage to the airplane included distortion of the fuselage and bending of both wing spars.

On May 22, 1995, a Federal Aviation Administration (FAA) inspector examined the airplane's brakes and found "they functioned good and had no defects." He also observed skid marks of both the left and right main gear tires on the runway leading to the point at which the airplane exited the runway. A copy of the inspector's statement is attached to this report.

Examination of the pilot's logbook by an FAA inspector revealed that the last logged flight was on October 2, 1994. The pilot completed a biennial flight review on March 12, 1994, and logged a total of 4.9 hours of flight time in 1994.

#### **Pilot Information**

Certificate:	Private	Age:	54,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 3, 1995
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	94 hours (Total, all aircraft), 6 hours (Total, this make and model), 51 hours (Pilot In Command, all aircraft), 1 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 FTW95LA210

## **Aircraft and Owner/Operator Information**

Aircraft Make:	CESSNA	Registration:	N7152M
Model/Series:	175 175	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	55452
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	February 18, 1995 Annual	Certified Max Gross Wt.:	2350 lbs
Time Since Last Inspection:	16 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2501 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	GO-300-A
Registered Owner:	MALVERN FLYERS, INC.	Rated Power:	
Operator:	KRATZ, WENDELL D.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

### **Meteorological Information and Flight Plan**

- Wicker Group Grown William	<u> </u>		
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	18°C
Precipitation and Obscuration:	No Obscuration; No Precipi	tation	
Departure Point:	(M78)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	19:30 Local	Type of Airspace:	Class G

Page 4 of 6 FTW95LA210

## **Airport Information**

Airport:	MALVERN MUNICIPAL M78	Runway Surface Type:	Asphalt
Airport Elevation:	538 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	3	IFR Approach:	None
Runway Length/Width:	3188 ft / 60 ft	VFR Approach/Landing:	Full stop

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.369476,-92.810501(est)

Page 5 of 6 FTW95LA210

#### **Administrative Information**

Investigator In Charge (IIC): Snyder, Georgia

Additional Participating Persons:

Original Publish Date: October 27, 1995

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=19428

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 FTW95LA210