



Aviation Investigation Final Report

Location: Gypsum, Colorado Accident Number: CEN24LA210

Date & Time: June 4, 2024, 20:12 Local Registration: N5755B

Aircraft: Cessna 182 Aircraft Damage: Substantial

Defining Event: Fuel exhaustion **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor and the pilot were conducting an instructional flight when the airplane had a total loss of engine power due to fuel exhaustion. The airplane fuselage sustained substantial damage during the forced landing in rough terrain. The flight instructor reported that there were no preimpact mechanical malfunctions or failures that would have precluded normal operation. The airplane operator reported that the fuel tanks remained intact after the accident, were void of usable fuel, and both fuel tank quantity gauges indicated empty.

Before the flight, the flight instructor asked another flight instructor to request the fixed based operator (FBO) to refuel the airplane. However, despite the fuel request being relayed to the FBO front desk personnel, the airplane was not fueled before it departed on the flight. The flight instructor and the pilot both admitted that they did not visually confirm the fuel quantity during their preflight inspection. Additionally, believing that the fuel tanks were topped-off as requested, the pilots erroneously reset the airplane's electronic fuel totalizer to reflect a full fuel load before takeoff.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The failure of the flight instructor and the pilot to visually confirm the airplane's fuel quantity during preflight, which resulted in a loss of engine power due to fuel exhaustion and an off-airport forced landing in rough terrain.

Findings

Aircraft Fuel - Fluid level

Aircraft Fuel - Inadequate inspection

Personnel issues Preflight inspection - Pilot

Personnel issues Preflight inspection - Instructor/check pilot

Environmental issues Rough terrain - Contributed to outcome

Page 2 of 6 CEN24LA210

Factual Information

History of Flight

Enroute	Fuel exhaustion (Defining event)
Landing	Off-field or emergency landing
Landing	Hard landing

Flight instructor Information

Certificate:	Commercial; Flight instructor	Age:	24,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	April 5, 2022
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	February 4, 2024
Flight Time:	459 hours (Total, all aircraft), 25 hours (Total, this make and model), 392 hours (Pilot In Command, all aircraft), 171 hours (Last 90 days, all aircraft), 85 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Private	Age:	32,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	June 17, 2021
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 29, 2023
Flight Time:	156 hours (Total, all aircraft), 63 hours (Total, this make and model), 78 hours (Pilot In Command, all aircraft), 54 hours (Last 90 days, all aircraft), 25 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CEN24LA210

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N5755B
Model/Series:	182	Aircraft Category:	Airplane
Year of Manufacture:	1956	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	33755
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	June 3, 2024 100 hour	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:	10 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	8136 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	C126 installed, activated, aided in locating accident	Engine Model/Series:	0-470-S
Registered Owner:	iTechnology Design Inc	Rated Power:	230 Horsepower
Operator:	Alpine Flight Training	Operating Certificate(s) Held:	None
		i iciu.	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	EGE,6535 ft msl	Distance from Accident Site:	2 Nautical Miles
Observation Time:	19:56 Local	Direction from Accident Site:	167°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots / None	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.11 inches Hg	Temperature/Dew Point:	23°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Eagle, CO (EGE)	Type of Flight Plan Filed:	None
Destination:	Eagle, CO (EGE)	Type of Clearance:	None
Departure Time:	17:53 Local	Type of Airspace:	Class E

Page 4 of 6 CEN24LA210

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	39.688969,-106.92878(est)

Page 5 of 6 CEN24LA210

Administrative Information

Investigator In Charge (IIC):	Fox, Andrew
Additional Participating Persons:	Michael R. Coryer; Federal Aviation Administration - Denver FSDO; Denver, CO
Original Publish Date:	January 21, 2025
Last Revision Date:	
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=194400

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CEN24LA210