



# Aviation Investigation Final Report

<b>Location:</b>	WELLINGTON, Colorado	<b>Accident Number:</b>	FTW95LA279
<b>Date &amp; Time:</b>	July 8, 1995, 13:30 Local	<b>Registration:</b>	N57669
<b>Aircraft:</b>	BELLANCA 8GCBC	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation		

## Analysis

DURING TOUCHDOWN FOR LANDING AT THE COMPLETION OF A GLIDER TOW FLIGHT, THE LEFT MAIN LANDING GEAR SEPARATED FROM THE AIRCRAFT, JUST OUTBOARD FROM THE FUSELAGE ATTACH POINT. EXAMINATION OF THE FRACTURE AREA REVEALED THAT THE SPRING GEAR HAD FAILED FROM FATIGUE. THERE WAS EVIDENCE THAT GRINDING HAD BEEN PERFORMED ON THE SPRING GEAR (DURING MAINTENANCE), WHICH RESULTED IN OVERHEATING OF THE STEEL AND SUBSEQUENT CHANGES IN ITS MICROSTRUCTURE.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FATIGUE FAILURE OF THE LEFT MAIN LANDING GEAR (SPRING STRUT), DUE TO THE IMPROPER MAINTENANCE (GRINDING) BY UNKNOWN MAINTENANCE PERSONNEL.

## Findings

Occurrence #1: GEAR COLLAPSED  
Phase of Operation: LANDING - ROLL

### Findings

1. (C) MAINTENANCE - IMPROPER - OTHER MAINTENANCE PERSONNEL
2. (C) LANDING GEAR, MAIN GEAR STRUT - FATIGUE

## Factual Information

On July 8, 1995, at 1330 mountain daylight time, a Bellanca 8GCBC, N57669, sustained substantial damage when the left main landing gear failed during landing roll at Owl Canyon Glider Park, Wellington, Colorado. The commercial pilot was not injured. Visual meteorological conditions prevailed for this local area glider tow flight operating under Title 14 CFR Part 91. The flight originated at 1320 and a flight plan was not filed.

According to the pilot, his landing sequence following the glider release contained "a mild bounce." The pilot said he added power for the second touch down and when touch down occurred the left main landing gear separated from the aircraft.

Examination of the aircraft by the investigator-in-charge provided evidence that the landing gear was of the spring steel type. Separation occurred just outboard of the fuselage attach point and during the ground excursion following the separation, the left wing, wing strut, left elevator, wind screen, left side window and propeller sustained damage.

Examination of the fracture surface by the NTSB Metallurgical Laboratory provided evidence of a fatigue failure and evidence that the landing gear spring steel had been ground at some point in time which caused overheating of the steel and subsequent changes in the microstructure. It was the metallurgist's evaluation, that the grinding initiated the fatigue. The metallurgist's report is attached.

### Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	49, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Front
<b>Other Aircraft Rating(s):</b>	Glider	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical--w/ waivers/lim	<b>Last FAA Medical Exam:</b>	February 14, 1995
<b>Occupational Pilot:</b>	UNK	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	1113 hours (Total, all aircraft), 207 hours (Total, this make and model), 1056 hours (Pilot In Command, all aircraft), 32 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	BELLANCA	<b>Registration:</b>	N57669
<b>Model/Series:</b>	8GCBC 8GCBC	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	2-74
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	June 7, 1995 Annual	<b>Certified Max Gross Wt.:</b>	2150 lbs
<b>Time Since Last Inspection:</b>	35 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	4692 Hrs	<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	O-360-C2E
<b>Registered Owner:</b>	COLORADO SOARING ASSOCIATION	<b>Rated Power:</b>	180 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	FNL ,5525 ft msl	<b>Distance from Accident Site:</b>	15 Nautical Miles
<b>Observation Time:</b>	12:35 Local	<b>Direction from Accident Site:</b>	180°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	6 knots / 15 knots	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	10°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30 inches Hg	<b>Temperature/Dew Point:</b>	32°C / 3°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	(4C02)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	13:20 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>	OWL CANYON GLIDER PARK 4C02	<b>Runway Surface Type:</b>	Grass/turf
<b>Airport Elevation:</b>	5545 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	1	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	2000 ft / 40 ft	<b>VFR Approach/Landing:</b>	Full stop

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	40.699756,-105.000328(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Wiemeyer, Norman
<b>Additional Participating Persons:</b>	DON BORDONARO; DENVER , CO
<b>Original Publish Date:</b>	January 29, 1996
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=19482">https://data.ntsb.gov/Docket?ProjectID=19482</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).