

Aviation Investigation Final Report

Location:	MCALLEN, Texas		Accident Number:	FTW83LA268
Date & Time:	June 6, 1983, 09:45	Local	Registration:	N4016Y
Aircraft:	CESSNA	185	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 Serious
Flight Conducted Under:	Part 91: General avia	ation - Personal		

Analysis

THE ENG QUIT DURING CLIMBOUT. INSPECTION REVEALED THAT THE FUEL SYSTEM CONTAINED ABOUT 50% CLEAR LIQUID OTHER THAN GASOLINE. THE ACFT HAD SAT WITH ITS TANKS EMPTY FOR THE PAST 7-10 DAYS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings 1. (C) FLUID,FUEL - WATER

Occurrence #2: FORCED LANDING Phase of Operation: MANEUVERING - TURN TO LANDING AREA (EMERGENCY)

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: MANEUVERING - TURN TO LANDING AREA (EMERGENCY)

Factual Information

Pilot Information

Certificate:	Commercial	Age:	53,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	September 30, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	15586 hours (Total, all aircraft), 2500 hours (Total, this make and model), 15501 hours (Pilot In Command, all aircraft), 46 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N4016Y
		-	1140101
Model/Series:	185 185	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	185-0216
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	February 22, 1983 Annual	Certified Max Gross Wt.:	3200 lbs
Time Since Last Inspection:	42 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1400 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	IO-470-F
Registered Owner:	W. A. CROSS	Rated Power:	260 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MFE ,107 ft msl	Distance from Accident Site:	
Observation Time:	09:48 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 1500 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	13 knots / 20 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	150°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	29°C / 24°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	VFR
Destination:		Type of Clearance:	
Departure Time:	09:45 Local	Type of Airspace:	Class A

Airport Information

Airport:	MILLER INTERNATIONAL MFE	Runway Surface Type:	Asphalt
Airport Elevation:	107 ft msl	Runway Surface Condition:	Dry
Runway Used:	18	IFR Approach:	None
Runway Length/Width:	3000 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	26.210182,-98.229393(est)

Administrative Information

Investigator In Charge (IIC):	Johnson, J.
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=20925

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.