

Aviation Investigation Final Report

| Location: | RUSTON, Louisiana | | Accident Number: | FTW88LA133 |
|-------------------------|--------------------------------------|-------|----------------------|------------|
| Date & Time: | July 17, 1988, 15:00 | Local | Registration: | N295C |
| Aircraft: | CESSNA | 310B | Aircraft Damage: | Minor |
| Defining Event: | | | Injuries: | 1 None |
| Flight Conducted Under: | Part 91: General aviation - Personal | | | |

Analysis

BOTH AIRPLANES WERE IN THE TRAFFIC PATTERN. THE CESSNA 152 MADE RADIO CALLS IN THE BLIND; THE CESSNA 310 DID NOT. BOTH AIRPLANES WERE ON FINAL AT THE SAME TIME WITH THE 152 IN THE LEAD AND THE 310 LOWER. THE 310 PASSED THE 152 JUST BEFORE TOUCHDOWN. THE 310 WAS ON THE GROUND AS THE 152 ROUNDED OUT RIGHT BEHIND IT. THE PILOTS IN THE 152 THEN SAW THE 310, ADDED FULL POWER, AND PULLED UP. THE LEFT HORIZONTAL STABILIZER OF THE 152 STRUCK THE VERTICAL STABILIZER OF THE 310. THE 310 STOPPED AND THE 152 LANDED IN FRONT OF THE 310 ON THE SAME RWY.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: LANDING - ROLL

Findings

1. (F) OBJECT - AIRCRAFT MOVING ON GROUND

2. (C) PROCEDURES/DIRECTIVES - NOT FOLLOWED - PILOT IN COMMAND

3. (C) VISUAL LOOKOUT - IMPROPER - PILOT IN COMMAND4. (F) COMMUNICATIONS - INADEQUATE - PILOT IN COMMAND

Factual Information

Pilot Information

| Certificate: | Private | Age: | 41,Male |
|---------------------------|---|------------------------|------------------|
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 Valid Medicalno waivers/lim. | Last FAA Medical Exam: | January 27, 1987 |
| Occupational Pilot: | No Last Flight Review or Equivalent: | | |
| Flight Time: | 378 hours (Total, all aircraft), 77 hours (Total, this make and model), 378 hours (Pilot In Command, all aircraft), 21 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | CESSNA | Registration: | N295C |
|----------------------------------|--------------------------|-----------------------------------|-----------------|
| Model/Series: | 310B 310B | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 35679 |
| Landing Gear Type: | Retractable - Tricycle | Seats: | 5 |
| Date/Type of Last Inspection: | Annual | Certified Max Gross Wt.: | 4700 lbs |
| Time Since Last Inspection: | 37 Hrs | Engines: | 2 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | CONTINENTAL |
| ELT: | Installed, not activated | Engine Model/Series: | 0-470-M |
| Registered Owner: | JACKSON B. COOPER | Rated Power: | 240 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|------------------------------|---|----------|
| conditions at Accident Site. | | Condition of Light. | Day |
| Observation Facility, Elevation: | | Distance from Accident Site: | |
| Observation Time: | | Direction from Accident Site: | |
| Lowest Cloud Condition: | Scattered / 3500 ft AGL | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 5 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 215° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | | Temperature/Dew Point: | 36°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ation | |
| Departure Point: | ST. JOSEPH , LA (L33) | Type of Flight Plan Filed: | None |
| Destination: | | Type of Clearance: | None |
| Departure Time: | 14:30 Local | Type of Airspace: | Class G |

Airport Information

| Airport: | MUNICIPAL RSN | Runway Surface Type: | Asphalt |
|----------------------|-----------------|---------------------------|---------------------------|
| Airport Elevation: | 327 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 16 | IFR Approach: | None |
| Runway Length/Width: | 4000 ft / 90 ft | VFR Approach/Landing: | Full stop;Traffic pattern |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Minor |
|------------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 32.529861,-92.630355(est) |

Administrative Information

| Investigator In Charge (IIC): | Roth, E. | | |
|--------------------------------------|--|--|--|
| Additional Participating Persons: | MYRON K HIRANO; BATON ROUGE , LA | | |
| Original Publish Date: | July 10, 1989 | | |
| Last Revision Date: | | | |
| Investigation Class: | <u>Class</u> | | |
| Note: | | | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=22660 | | |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.



Aviation Investigation Final Report

| Location: | RUSTON, Louisiana | | Accident Number: | FTW88LA133 |
|-------------------------|---|-------|----------------------|-------------|
| Date & Time: | July 17, 1988, 15:00 | Local | Registration: | N93294 |
| Aircraft: | CESSNA | 152 | Aircraft Damage: | Substantial |
| Defining Event: | | | Injuries: | 2 None |
| Flight Conducted Under: | Part 91: General aviation - Instructional | | | |

Analysis

BOTH AIRPLANES WERE IN THE TRAFFIC PATTERN. THE CESSNA 152 MADE RADIO CALLS IN THE BLIND; THE CESSNA 310 DID NOT. BOTH AIRPLANES WERE ON FINAL AT THE SAME TIME WITH THE 152 IN THE LEAD AND THE 310 LOWER. THE 310 PASSED THE 152 JUST BEFORE TOUCHDOWN. THE 310 WAS ON THE GROUND AS THE 152 ROUNDED OUT RIGHT BEHIND IT. THE PILOTS IN THE 152 THEN SAW THE 310, ADDED FULL POWER, AND PULLED UP. THE LEFT HORIZONTAL STABILIZER OF THE 152 STRUCK THE VERTICAL STABILIZER OF THE 310. THE 310 STOPPED AND THE 152 LANDED IN FRONT OF THE 310 ON THE SAME RWY.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) OBJECT - AIRCRAFT MOVING ON GROUND 2. (C) PROCEDURES/DIRECTIVES - NOT FOLLOWED - PILOT OF OTHER AIRCRAFT 3. (C) VISUAL LOOKOUT - IMPROPER - PILOT OF OTHER AIRCRAFT 4. (F) COMMUNICATIONS - INADEQUATE - PILOT OF OTHER AIRCRAFT

Factual Information

Pilot Information

| Certificate: | Commercial; Flight instructor | Age: | 25,Male |
|---------------------------|---|-----------------------------------|---------------|
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Right |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | Yes |
| Instructor Rating(s): | Airplane multi-engine; Airplane single-engine | Toxicology Performed: | No |
| Medical Certification: | Class 2 Valid Medical–no waivers/lim. | Last FAA Medical Exam: | April 7, 1988 |
| Occupational Pilot: | Yes | Last Flight Review or Equivalent: | |
| Flight Time: | 1141 hours (Total, all aircraft), 341 hours (Total, this make and model), 938 hours (Pilot In Command, all aircraft), 58 hours (Last 90 days, all aircraft), 14 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | CESSNA | Registration: | N93294 |
|----------------------------------|---------------------------|-----------------------------------|-----------------|
| Model/Series: | 152 152 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Utility | Serial Number: | 15285461 |
| Landing Gear Type: | Tricycle | Seats: | 2 |
| Date/Type of Last Inspection: | May 10, 1988 Annual | Certified Max Gross Wt.: | 1600 lbs |
| Time Since Last Inspection: | 97 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | LYCOMING |
| ELT: | Installed, not activated | Engine Model/Series: | 0-235-L2C |
| Registered Owner: | MCMAHAN AVIATION | Rated Power: | 110 Horsepower |
| Operator: | LOUISIANA TECH UNIVERSITY | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Meteorological Information and Flight Plan

| Oanditions at Assidant City | Viewel () () () () | Opendition of Links | Dev |
|---|------------------------------|---|----------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | | Distance from Accident Site: | |
| Observation Time: | | Direction from Accident Site: | |
| Lowest Cloud Condition: | Scattered / 3500 ft AGL | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 5 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 215° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | | Temperature/Dew Point: | 36°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ation | |
| Departure Point: | (RSN) | Type of Flight Plan Filed: | None |
| Destination: | | Type of Clearance: | None |
| Departure Time: | 14:00 Local | Type of Airspace: | Class G |

Airport Information

| Airport: | MUNICIPAL RSN | Runway Surface Type: | Asphalt |
|----------------------|-----------------|---------------------------|---------------------------|
| Airport Elevation: | 327 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 16 | IFR Approach: | None |
| Runway Length/Width: | 4000 ft / 90 ft | VFR Approach/Landing: | Full stop;Traffic pattern |

Wreckage and Impact Information

| Crew Injuries: | 2 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|---------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 32.529861,-92.630355(est) |

Administrative Information

| Investigator In Charge (IIC): | Roth, E. |
|--------------------------------------|--|
| Additional Participating Persons: | MYRON K HIRANO; BATON ROUGE , LA |
| Original Publish Date: | July 10, 1989 |
| Last Revision Date: | |
| Investigation Class: | <u>Class</u> |
| Note: | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=22660 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.