



Aviation Investigation Final Report

Location: SIVELL BEND, Texas Accident Number: FTW90DPA03

Date & Time: May 8, 1990, 14:45 Local **Registration:** N25126

Aircraft: BELL-MOORE 47G-2A Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

WHILE FLYING OVER THE FIELD TO BE SPRAYED, THE HELICOPTER ENCOUNTERED A GUST OF WIND WHICH RESULTED IN A DESCENT. RECOVERY WAS ATTEMPTED BUT THE HELICOPTER WAS NOT ABLE TO CLIMB BEFORE IT IMPACTED TREES AND THE TERRAIN.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: CLEARANCE WAS NOT MAINTAINED BY THE PILOT-IN-COMMAND.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Findings

1. (C) CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

2. OBJECT - TREE(S)

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: DESCENT - UNCONTROLLED

Factual Information

Pilot Information

Certificate:	Airline transport; Commercial; Flight instructor; Private	Age:	43,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine; Helicopter; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	January 4, 1990
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	23000 hours (Total, all aircraft), 12000 hours (Total, this make and model), 22000 hours (Pilot In Command, all aircraft), 160 hours (Last 90 days, all aircraft), 130 hours (Last 30 days, all aircraft), 15 hours (Last 24 hours, all aircraft)		

Page 2 of 5 FTW90DPA03

Aircraft and Owner/Operator Information

Aircraft Make:	BELL-MOORE	Registration:	N25126
Model/Series:	47G-2A 47G-2A	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	H276
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	March 10, 1990 100 hour	Certified Max Gross Wt.:	2850 lbs
Time Since Last Inspection:	60 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1760 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	V0435-A1F
Registered Owner:	B & S FLYING SERVICE INC.	Rated Power:	275 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots / 15 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	170°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	25°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:42 Local	Type of Airspace:	Class G

Page 3 of 5 FTW90DPA03

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.630001,-97.150238(est)

Page 4 of 5 FTW90DPA03

Administrative Information

Investigator In Charge (IIC): Robinson, Kenneth

Additional Participating
Persons:

Original Publish Date: December 14, 1992

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=22929

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 FTW90DPA03