



Aviation Investigation Final Report

Location: CIRCLE HOT SPRI, Alaska Accident Number: ANC93LA117

Date & Time: July 14, 1993, 12:30 Local Registration: N4946M

Aircraft: PIPER PA-20 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

ACCORDING TO THE PILOT-IN-COMMAND HE FELT THERE WAS A ROCK JAMMED IN THE LEFT BRAKE OR WHEEL BECAUSE DURING HIS TAXI HE FELT THE LEFT WHEEL DRAGGING. HE ADDED POWER AND THE AIRPLANE TAXIED OVER SOME RUTS AT THE SAME TIME. THE AIRPLANE MADE A QUICK TURN AND LEFT THE SIDE OF THE RUNWAY STRIKING A TREE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT-IN-COMMAND'S FAILURE TO MAINTAIN DIRECTIONAL CONTROL DURING TAXI. FACTOR IS THE ROUGH/RUTTED CONDITION OF THE AIRSTRIP.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAXI - TO TAKEOFF

Findings

1. (F) TERRAIN CONDITION - ROUGH/UNEVEN

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: TAXI - TO TAKEOFF

Findings
3. OBJECT - TREE(S)

Page 2 of 6 ANC93LA117

Factual Information

On July 14, 1993, at 1230 Alaska daylight time, a wheel equipped Piper PA-20 airplane, N4946M, registered to and operated by the Pilot-in-Command, ran off the runway and struck a tree at Circle Hot Springs Airstrip, Circle Hot Springs, Alaska, while taxiing for takeoff. The personal flight, operating under 14 CFR Part 91 was taxiing for takeoff at Circle Hot Springs and the destination was Fairbanks, Alaska. A visual flight rules flight plan was filed and visual meteorological conditions prevailed. The airplane was substantially damaged and the Pilot-in-Command and his passenger were not injured.

According to the Pilot-in-Command during a telephone interview right after the accident, he felt the left wheel dragging during taxi and he added power. The airplane made a quick turn and ran off the side of the runway. According to the NTSB Form 6120.1/2 submitted by the Pilot-in-Command, he suspected that a rock had been jammed in the brake or wheel on the left side. He also stated that the wheels hit some ruts when he added power. He did not describe the width or depth of the ruts.

Pilot Information

| Certificate: | Private | Age: | 45,Male |
|---------------------------|---|-----------------------------------|----------------|
| Airplane Rating(s): | Single-engine land; Single-engine sea | Seat Occupied: | Front |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 Valid Medicalw/ waivers/lim | Last FAA Medical Exam: | March 10, 1992 |
| Occupational Pilot: | UNK | Last Flight Review or Equivalent: | |
| Flight Time: | 170 hours (Total, all aircraft), 45 hours (Total, this make and model), 170 hours (Pilot In Command, all aircraft), 11 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft) | | |

Page 3 of 6 ANC93LA117

Aircraft and Owner/Operator Information

| Aircraft Make: | PIPER | Registration: | N4946M |
|----------------------------------|-----------------------------|-----------------------------------|-----------------|
| Model/Series: | PA-20 PA-20 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 20-637 |
| Landing Gear Type: | Tailwheel | Seats: | 2 |
| Date/Type of Last Inspection: | July 1, 1992 Annual | Certified Max Gross Wt.: | 1800 lbs |
| Time Since Last Inspection: | 18 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 2490 Hrs | Engine Manufacturer: | Lycoming |
| ELT: | Installed, not activated | Engine Model/Series: | 0-290-D |
| Registered Owner: | HENRY & SANDRA GARBOWSKI | Rated Power: | 125 Horsepower |
| Operator: | GARBOWSKI, HENRY | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | | Condition of Light: | Day |
|----------------------------------|----------------|-------------|--------------------------------------|----------|
| Conditions at Accident Site. | visuai (vivic) | | Condition of Light. | Day |
| Observation Facility, Elevation: | | | Distance from Accident Site: | |
| Observation Time: | | | Direction from Accident Site: | |
| Lowest Cloud Condition: | Clear | | Visibility | 40 miles |
| Lowest Ceiling: | None | | Visibility (RVR): | |
| Wind Speed/Gusts: | / | | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 0° | | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | | | Temperature/Dew Point: | 27°C |
| Precipitation and Obscuration: | | | | |
| Departure Point: | | | Type of Flight Plan Filed: | VFR |
| Destination: | FAIRBANKS | , AK (FAI) | Type of Clearance: | None |
| Departure Time: | 12:30 Local | | Type of Airspace: | Class G |

Page 4 of 6 ANC93LA117

Airport Information

| Airport: | CIRCLE HOT SPRINGS CHP | Runway Surface Type: | Gravel |
|----------------------|------------------------|---------------------------|--------|
| Airport Elevation: | 956 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 0 | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | None |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|----------------------------|
| Passenger Injuries: | 1 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 65.790008,-144.200729(est) |

Page 5 of 6 ANC93LA117

Administrative Information

| Investigator In Charge (IIC): | Kobelnyk, George | | |
|-----------------------------------|---|--|--|
| Additional Participating Persons: | PHIL EVANS; FAIRBANKS , AK | | |
| Original Publish Date: | June 30, 1994 | | |
| Last Revision Date: | | | |
| Investigation Class: | <u>Class</u> | | |
| Note: | | | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=2379 | | |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC93LA117