



Aviation Investigation Final Report

Location: LOS BANOS, California Accident Number: LAX84LA010

Date & Time: October 10, 1983, 06:30 Local Registration: N4026G

Aircraft: HILLER UH12E Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

THE PLT LOADED THE HELICOPTER & STARTED A SPRAYING OPERATION. HE STATED THAT AS HE PULLED THE HELICOPTER UP FROM THE 1ST SPRAY RUN, IT STARTED SHAKING & WENT PARTIALLY OUT OF CONTROL. HE WAS ABLE TO REGAIN ENOUGH CONTROL TO GET THE HELICOPTER IN LEVEL FLT BEFORE IT STRUCK THE GROUND & WAS DAMAGED. NO PREIMPACT DISCREPANCIES WERE FOUND WHICH WOULD HAVE CONTRIBUTED TO THE ACCIDENT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING - AERIAL APPLICATION

Findings

1. MANEUVER - INITIATED - PILOT IN COMMAND

2. (C) AIRCRAFT HANDLING - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: MANEUVERING - AERIAL APPLICATION

Page 2 of 5 LAX84LA010

Factual Information

Pilot Information

Certificate:	Commercial	Age:	38,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	March 9, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	3290 hours (Total, all aircraft), 1520 hours (Total, this make and model), 2500 hours (Pilot In Command, all aircraft), 150 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	HILLER	Registration:	N4026G
Model/Series:	UH12E UH12E	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	5049
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	May 25, 1983 100 hour	Certified Max Gross Wt.:	3100 lbs
Time Since Last Inspection:	80 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1177 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	U0540
Registered Owner:	PATTERSON FLYING SERVICE	Rated Power:	305 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 LAX84LA010

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	25 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	225°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	18°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	LOS BANOS , CA	Type of Flight Plan Filed:	None
Destination:	LOS BANOS , CA	Type of Clearance:	None
Departure Time:	07:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.07048,-120.840385(est)

Page 4 of 5 LAX84LA010

Administrative Information

Investigator In Charge (IIC):	Schutte, Audrey
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=24057

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX84LA010