

# **Aviation Investigation Final Report**

Location:	BYRON, California		Accident Number:	LAX84LA477
Date & Time:	September 1, 1984	, 13:00 Local	<b>Registration:</b>	N77G
Aircraft:	PIPER	PA-22-135	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General av	iation - Personal		

### **Analysis**

DURING TAKEOFF, THE ENG LOST POWER AS THE ACFT WAS CLIMBING BETWEEN 400 & 600 FT. SUBSEQUENTLY, THE RIGHT GEAR COLLAPSED WHEN THE ACFT WAS LANDED ON ROLLING TERRAIN. THE PLT ESTIMATED THERE WAS ABOUT 2 GAL OF FUEL ON BOARD.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings 1. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND 2. (C) FLUID,FUEL - STARVATION 3. (C) FUEL SUPPLY - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING Phase of Operation: DESCENT - EMERGENCY Occurrence #3: MAIN GEAR COLLAPSED Phase of Operation: LANDING

# **Factual Information**

#### **Pilot Information**

Certificate:	Private	Age:	44,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Expired	Last FAA Medical Exam:	June 7, 1982
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	3000 hours (Total, all aircraft), 1000 hours (Total, this make and model), 10 hours (Last 90 days, all aircraft)		

#### Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N77G
Model/Series:	PA-22-135 PA-22-135	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	221210
Landing Gear Type:	Tailwheel	Seats:	
Date/Type of Last Inspection:	June 28, 1984 Annual	Certified Max Gross Wt.:	1950 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3771 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-235
Registered Owner:	JAMES R. LLOYD	Rated Power:	135 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

#### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
<b>Observation Facility, Elevation:</b>		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	12 knots / 15 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	225°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	34°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	BYRON , CA (4Q5)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	12:55 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	BYRON 4Q5	Runway Surface Type:	Dirt
Airport Elevation:		Runway Surface Condition:	Dry;Vegetation
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.850967,-121.620758(est)

#### Administrative Information

Investigator In Charge (IIC):	Pollack, Wayne	
Additional Participating Persons:	PAUL FLOOD; OAKLAND , CA	
Original Publish Date:		
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=24397	
	https://data.ntsb.gov/Docket?ProjectID=24397	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.