



Aviation Investigation Final Report

Location: SNELLING, California Accident Number: LAX85LA105

Date & Time: January 10, 1985, 16:40 Local Registration: N99021

Aircraft: BELL 204 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

PLT VACATED THE ACFT WITH ENGINE AT IDLE & WITH THE BLADES TURNING TO REFUEL. THE LANDING PLATFORM MOUNTED ON THE 'NURSE' TRUCK WAS SLIPPERY FROM AN OIL & COPPER MIXTURE USED IN THE SPRAYING OPERATION. THE HELICOPTER STARTED TO SLIDE & THE PLT REBOARDED JUST AS IT FELL OFF THE TRUCK.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: STANDING - IDLING ROTORS

Findings

1. (C) AIRCRAFT UNATTENDED/ENGINE(S) RUNNING - INTENTIONAL - PILOT IN COMMAND

2. (F) COMPLACENCY - PILOT IN COMMAND

3. (F) JUDGMENT - POOR - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Commercial	Age:	58,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Invalid Medical for flight	Last FAA Medical Exam:	December 31, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	30450 hours (Total, all aircraft), 1000 hours (Total, this make and model), 30450 hours (Pilot In Command, all aircraft), 55 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELL	Registration:	N99021
Model/Series:	204 204	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	64-13949
Landing Gear Type:	Skid	Seats:	
Date/Type of Last Inspection:	April 2, 1984 Annual	Certified Max Gross Wt.:	8600 lbs
Time Since Last Inspection:		Engines:	1 Turbo shaft
Airframe Total Time:	36829 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	653-11
Registered Owner:	BETTENCOURT FLYING SERVICE INC	Rated Power:	1100 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 LAX85LA105

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MER,153 ft msl	Distance from Accident Site:	18 Nautical Miles
Observation Time:	16:55 Local	Direction from Accident Site:	185°
Lowest Cloud Condition:	Scattered / 3000 ft AGL	Visibility	6 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	1 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	9°C / 5°C
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	DELHI , CA	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.540985,-120.450645(est)

Page 3 of 4 LAX85LA105

Administrative Information

Investigator In Charge (IIC): Pyatt, M

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=24630

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 LAX85LA105