



Aviation Investigation Final Report

Location: DELANO, California Accident Number: LAX86DVA09

Date & Time: June 17, 1986, 10:30 Local Registration: N172ET

Aircraft: HILLER UH-12E Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Positioning

Analysis

THE HELICOPTER ROTOR BLADE DELAMINATED SHORTLY AFTER DEPARTING THE OPERATOR'S NORTH BASE AT DELANO, CA. THE INVESTIGATION DETERMINED THE BLADE CONTAINED EXTENSIVE VOIDS ON THE BOND LINE. THE BLADE WAS REJECTED BY THE MANUFACTURER AS BEING UNAIRWORTHY. THE OPERATOR BOUGHT THE BLADE IN AN AS IS CONDITION. THE OPERATOR COULD NOT PRODUCE ANY YELLOW SERVICEABLE TAGS. INVESTIGATOR'S COULD NOT DETERMINE WHO OVERHAULED THE BLADES.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) ROTOR SYSTEM, MAIN ROTOR BLADE - FAILURE, PARTIAL

2. (C) MAINTENANCE, MAJOR REPAIR - IMPROPER - COMPANY MAINTENANCE PERSONNEL

Occurrence #2: LOSS OF CONTROL - IN FLIGHT Phase of Operation: TAKEOFF - INITIAL CLIMB

Occurrence #3: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Findings

3. AUTOROTATION - PERFORMED - PILOT IN COMMAND

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Page 2 of 5 LAX86DVA09

Factual Information

Pilot Information

Certificate:	Commercial	Age:	42,Male
Airplane Rating(s):	None	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	October 31, 1985
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	10000 hours (Total, all aircraft), 300 hours (Total, this make and model), 10000 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	HILLER	Registration:	N172ET
Model/Series:	UH-12E UH-12E	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	HA3072
Landing Gear Type:	Retractable - Tricycle	Seats:	3
Date/Type of Last Inspection:	March 11, 1986 100 hour	Certified Max Gross Wt.:	3100 lbs
Time Since Last Inspection:	100 Hrs	Engines:	1 Turbo shaft
Airframe Total Time:	2690 Hrs	Engine Manufacturer:	ALLISON
ELT:	Not installed	Engine Model/Series:	250-C20
Registered Owner:	SAN JOAQUIN HELICOPTERS	Rated Power:	301 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 LAX86DVA09

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:	RIVERSIDE , CA (RAL)	Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

Airport Information

Airport:	DELANO DLO	Runway Surface Type:	Dirt
Airport Elevation:	313 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 4 of 5 LAX86DVA09

Administrative Information

De costa, Larry Investigator In Charge (IIC): **Additional Participating ROBYN** MCDONOUGH; FRESNO Persons: SAM BRODIE; FORT WORTH , TX **Original Publish Date:** April 25, 1988 **Last Revision Date:** Investigation Class: Class Note: **Investigation Docket:** https://data.ntsb.gov/Docket?ProjectID=24866

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX86DVA09