



Aviation Investigation Final Report

Location: NOATAK, Alaska Accident Number: ANC94LA083

Date & Time: July 16, 1994, 12:00 Local Registration: N8287Q

Aircraft: CESSNA 206 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 135: Air taxi & commuter - Non-scheduled

Analysis

THE PILOT 'DRAGGED' THE GRAVEL BAR, LOCATED ON THE KELLY RIVER, THREE TIMES AND DID NOT SEE ANYTHING UNUSUAL. HE HAD LANDED IN THAT AREA DURING THREE PREVIOUS FLIGHTS. HE LANDED ON THE GRAVEL BAR AND DURING THE LANDING ROLL OUT THE AIRPLANE STRUCK A 'CUT BANK.' THE AIRPLANE'S NOSE GEAR WAS SHEARED AND THE MAIN LANDING GEAR WAS PUSHED REARWARD. THE COLOR OF THE GRAVEL IN THE LANDING AREA AND THE 'CUT BANK' WERE THE SAME.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S SELECTION OF UNSUITABLE LANDING AREA. A FACTOR WAS A 'CUT BANK' IN THE LANDING AREA.

Findings

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - SELECTED - PILOT IN COMMAND

2. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION - DITCH

Occurrence #2: GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Page 2 of 6 ANC94LA083

Factual Information

On July 16, 1994, at 1200 Alaska daylight time, a wheel equipped Cessna 206 airplane, registered to and operated by Northwestern Aviation of Kotzebue, Alaska, struck a "cut bank" while landing on a gravel bar on the Kelly River, 100 miles north of Kotzebue. The Air Taxi flight, operating under 14 CFR Part 135, departed Kotzebue on a VFR flight plan and the destination was the accident site. Visual meteorological conditions prevailed. The pilot and the passenger were not injured and the airplane was substantially damaged.

According to the pilot, he had landed on the gravel before but he still "dragged" the strip three times before this landing. He dragged the strip each time at a lower altitude ending with 500 feet. He could not see the "cut bank" during his observations of the landing area. During the roll out the airplane struck the cut bank. The cut bank was approximately 3 to 4 feet deep and was composed of the same material as the rest of the gravel bar.

The airplane's nose gear sheared just above the fork attach points and the main landing gear was pushed rearward causing damage to the fuselage gear box attaching structure.

According to information provided by the Federal Aviation Administration Airman Certification Branch in Oklahoma City, Oklahoma, the pilot applied for an additional aircraft category rating on May 6, 1994. The pilot listed that he had a total time of 3800 hours in airplanes and 35 hours in helicopters. He was issued a rotorcraft/helicopter rating which fulfilled the additional requirement for a Biennial Flight Review.

Pilot Information

Certificate:	Commercial; Private	Age:	52,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider; Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 2, 1994
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	3835 hours (Total, all aircraft), 3313 hours (Pilot In Command, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC94LA083

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N8287Q
Model/Series:	206 206	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	U20603148
Landing Gear Type:	Tricycle	Seats:	6
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, aided in locating accident	Engine Model/Series:	IO-520
Registered Owner:	NORTHWESTERN AVIATION	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	FWHC

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	90 miles
Lowest Ceiling:	Broken / 10000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	11 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	24°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	KOTZEBUE , AK (OTZ)	Type of Flight Plan Filed:	VFR
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Page 4 of 6 ANC94LA083

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used: 0)	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	67.569686,-162.999908(est)

Page 5 of 6 ANC94LA083

Administrative Information

Investigator In Charge (IIC):	Kobelnyk, George	
Additional Participating Persons:	STEVE KETZER; FAIRBANKS , AK	
Original Publish Date:	May 9, 1995	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=2523	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC94LA083