



Aviation Investigation Final Report

Location: PHOENIX, Arizona Accident Number: LAX88FA196

Date & Time: May 29, 1988, 17:40 Local Registration: N904Q

Aircraft: BEECH H-35 Aircraft Damage: Destroyed

Defining Event: 1 Fatal

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT HAD JUST COMPLETED A FLIGHT FROM FARMINGTON, N.M., TO PHOENIX, AZ (PHX) WHERE SHE DEPLANED HER PAX. THE PLT DEPT PHX ENROUTE TO MESA, AZ, (FFZ). AFTER T.O. THE LCL CONTROLLER INSTRUCTED THE PLT TO TURN RIGHT TO 300 DEG AND TO TURN ON THE XPNDR; THE PLT COMPLIED. SHORTLY THEREAFTER THE LCL CONTROLLER INSTRUCTED THE PLT TO CONTACT THE DEPT CONTROLLER. THE PLT DID NOT ACKNOWLEDGE OR COMPLY WITH THE INSTRUCTIONS. GND WITNESSES RPTD THAT THE AIRPLANE WAS FLYING AT A LOW ALTITUDE WHEN IT PITCHED OVER & CRASHED. THE INVESTIGATION DSCLD NO EVIDENCE OF ANY PREIMPACT AIRFRAME/ENGINE MALFUNCTIONS. THE CABIN ENTRANCE DOOR WAS FOUND TO BE OPEN AT IMPACT, BUT THE LATCHING MECHANISM WAS IN THE LOCKED POSITION. THE PLT'S POSTMORTEM EXAM DISCLOSED THAT SHE WAS NOT WEARING A SEAT BELT AT THE TIME & HER RT ARM WAS EXTENDED AT IMPACT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: CLIMB - TO CRUISE

Findings

- 1. (C) DOOR, PASSENGER UNLOCKED
- 2. (C) AIRCRAFT PREFLIGHT INADEQUATE PILOT IN COMMAND
- 3. (F) ACFT/EQUIP, INADEQUATE DESIGN MANUFACTURER

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: DESCENT - UNCONTROLLED

Findings

- 4. (C) ALTITUDE NOT MAINTAINED PILOT IN COMMAND
- 5. (F) DIVERTED ATTENTION PILOT IN COMMAND

Page 2 of 5 LAX88FA196

Factual Information

Pilot Information

| Certificate: | Private | Age: | 24,Female |
|---------------------------|--|---|--------------------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | Yes |
| Medical Certification: | Class 3 Valid Medicalw/ waivers/lim | Last FAA Medical Exam: | November 7, 1986 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | |
| Flight Time: | 650 hours (Total, all aircraft), 150 ho aircraft) | ours (Total, this make and model), 3 ho | ours (Last 24 hours, all |

Aircraft and Owner/Operator Information

| Aircraft Make: | BEECH | Registration: | N904Q |
|-------------------------------|--------------------------|-----------------------------------|-----------------|
| Model/Series: | H-35 H-35 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | D-5084 |
| Landing Gear Type: | Retractable - Tricycle | Seats: | 4 |
| Date/Type of Last Inspection: | November 11, 1987 Annual | Certified Max Gross Wt.: | 2900 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 2500 Hrs | Engine Manufacturer: | CONTINENTAL |
| ELT: | Installed, not activated | Engine Model/Series: | 0-470-G |
| Registered Owner: | JOHN E. CASSIDY | Rated Power: | 240 Horsepower |
| Operator: | DAVID B. CASSIDY | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Page 3 of 5 LAX88FA196

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|----------------------------------|--------------------------------------|------------------|
| Observation Facility, Elevation: | PHX ,1132 ft msl | Distance from Accident Site: | 2 Nautical Miles |
| Observation Time: | 17:58 Local | Direction from Accident Site: | 120° |
| Lowest Cloud Condition: | Scattered / 6000 ft AGL | Visibility | 7 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 20 knots / 27 knots | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 280° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 29 inches Hg | Temperature/Dew Point: | 26°C / -6°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | PHOENIX , AZ (PHX) | Type of Flight Plan Filed: | None |
| Destination: | MESA , AZ (FFZ) | Type of Clearance: | None |
| Departure Time: | 17:39 Local | Type of Airspace: | Class D |

Airport Information

| Airport: | PHOENIX PHX | Runway Surface Type: | |
|----------------------|-------------|----------------------------------|------|
| Airport Elevation: | 1132 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 0 | IFR Approach: | None |
| Runway Length/Width: | 0 ft / 0 ft | VFR Approach/Landing: | None |

Wreckage and Impact Information

| Crew Injuries: | 1 Fatal | Aircraft Damage: | Destroyed |
|------------------------|---------|-------------------------|----------------------------|
| Passenger Injuries: | | Aircraft Fire: | On-ground |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 Fatal | Latitude, Longitude: | 33.500331,-112.049064(est) |

Page 4 of 5 LAX88FA196

Administrative Information

Investigator In Charge (IIC): Llorente, A. **Additional Participating BARRY** J PHILLIPS; PHOENIX , AZ Persons: JOHN E WARD; JOHN KENT; **Original Publish Date:** June 9, 1989 **Last Revision Date: Investigation Class:** Class Note: **Investigation Docket:** https://data.ntsb.gov/Docket?ProjectID=25835

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX88FA196