



# **Aviation Investigation Final Report**

Location: VISALIA, California Accident Number: LAX88LA279

Date & Time: August 3, 1988, 15:30 Local Registration: N9273M

Aircraft: MOONEY M20E Aircraft Damage: Substantial

**Defining Event:** 4 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

THE PILOT REMOVED THE VACUUM PUMP FROM THE ENGINE PRIOR TO THE FLIGHT BECAUSE OF AN INTERNAL FAILURE IN THE PUMP. THE PILOT DID NOT INSTALL A COVER PLATE ON THE ACCESSORY MOUNTING HOLE VACATED BY THE PUMP. AFTER TAKEOFF ON THE LOCAL FLIGHT, THE PILOT NOTICED THE OIL PRESSURE WAS DROPPING AND THE TEMPERATURE WAS RISING. HE ELECTED TO RETURN TO THE AIRPORT. THE ENGINE SIEZED AND THE PILOT MADE A FORCED LANDING IN A COTTON FIELD.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: DESCENT - NORMAL

#### **Findings**

1. (C) ENGINE ACCESSORIES, VACUUM PUMP - LACK OF

- 2. (C) FLUID, OIL LOSS, TOTAL
- 3. (C) ENGINE ASSEMBLY SEIZED
- 4. (C) MAINTENANCE, MODIFICATION IMPROPER PILOT IN COMMAND

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### Findings

5. (F) TERRAIN CONDITION - NONE SUITABLE 6. (F) TERRAIN CONDITION - HIGH VEGETATION

Page 2 of 5 LAX88LA279

## **Factual Information**

### **Pilot Information**

| Certificate:              | Private   | Age:                              | 55,Male       |
|---------------------------|---|-----------------------------------|---------------|
| Airplane Rating(s):       | Single-engine land  | Seat Occupied:                    | Left          |
| Other Aircraft Rating(s): | None  | Restraint Used:                   |               |
| Instrument Rating(s):     | None  | Second Pilot Present:             | No            |
| Instructor Rating(s):     | None  | Toxicology Performed:             | No            |
| Medical Certification:    | Class 3 Valid Medicalw/<br>waivers/lim  | Last FAA Medical Exam:            | July 22, 1988 |
| Occupational Pilot:       | No  | Last Flight Review or Equivalent: |               |
| Flight Time:              | 531 hours (Total, all aircraft), 466 hours (Total, this make and model), 500 hours (Pilot In Command, all aircraft), 16 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) |                                   |               |

## Aircraft and Owner/Operator Information

| Aircraft Make:                | MOONEY                    | Registration:                     | N9273M          |
|-------------------------------|---------------------------|-----------------------------------|-----------------|
| Model/Series:                 | M20E M20E                 | Aircraft Category:                | Airplane        |
| Year of Manufacture:          |                           | Amateur Built:                    |                 |
| Airworthiness Certificate:    | Normal                    | Serial Number:                    | 1212            |
| Landing Gear Type:            | Retractable - Tricycle    | Seats:                            | 4               |
| Date/Type of Last Inspection: | September 16, 1987 Annual | Certified Max Gross Wt.:          | 2575 lbs        |
| Time Since Last Inspection:   | 35 Hrs                    | Engines:                          | 1 Reciprocating |
| Airframe Total Time:          | 1629 Hrs                  | Engine Manufacturer:              | LYCOMING        |
| ELT:                          | Installed, not activated  | Engine Model/Series:              | IO-360-A1A      |
| Registered Owner:             | ITZACO, INC               | Rated Power:                      | 200 Horsepower  |
| Operator:                     | STANFORD, WILLIAM L.      | Operating Certificate(s)<br>Held: | None            |
| Operator Does Business As:    |                           | Operator Designator Code:         |                 |

Page 3 of 5 LAX88LA279

### Meteorological Information and Flight Plan

| Conditions at Accident Site:     | Visual (VMC)                 | Condition of Light:                  | Day      |
|----------------------------------|------------------------------|--------------------------------------|----------|
| Observation Facility, Elevation: |                              | Distance from Accident Site:         |          |
| Observation Time:                |                              | Direction from Accident Site:        |          |
| <b>Lowest Cloud Condition:</b>   | Clear                        | Visibility                           | 15 miles |
| Lowest Ceiling:                  | None                         | Visibility (RVR):                    |          |
| Wind Speed/Gusts:                | 5 knots /                    | Turbulence Type<br>Forecast/Actual:  | /        |
| Wind Direction:                  | 300°                         | Turbulence Severity Forecast/Actual: | /        |
| Altimeter Setting:               |                              | Temperature/Dew Point:               |          |
| Precipitation and Obscuration:   | No Obscuration; No Precipita | ation                                |          |
| Departure Point:                 | (VIS)                        | Type of Flight Plan Filed:           | None     |
| Destination:                     | (VIS)                        | Type of Clearance:                   | None     |
| Departure Time:                  | 15:25 Local                  | Type of Airspace:                    | Class G  |

## **Airport Information**

| Airport:             | VIS         | Runway Surface Type:             | Dirt           |
|----------------------|-------------|----------------------------------|----------------|
| Airport Elevation:   | 292 ft msl  | <b>Runway Surface Condition:</b> | Vegetation     |
| Runway Used:         | 0           | IFR Approach:                    | None           |
| Runway Length/Width: | 0 ft / 0 ft | VFR Approach/Landing:            | Forced landing |

## Wreckage and Impact Information

| Crew Injuries:         | 1 None | Aircraft Damage:        | Substantial                |
|------------------------|--------|-------------------------|----------------------------|
| Passenger<br>Injuries: | 3 None | Aircraft Fire:          | None                       |
| Ground Injuries:       | N/A    | Aircraft Explosion:     | None                       |
| Total Injuries:        | 4 None | Latitude,<br>Longitude: | 36.289882,-119.379516(est) |

Page 4 of 5 LAX88LA279

#### **Administrative Information**

Investigator In Charge (IIC): Rich, Jeff

Additional Participating Persons: MAURICE FULKERSON; FRESNO , CA

Original Publish Date: November 7, 1989

Last Revision Date: Investigation Class: Class

Note: https://data.ntsb.gov/Docket?ProjectID=26073

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX88LA279