



# **Aviation Investigation Final Report**

Location: HOLLISTER, California Accident Number: LAX89LA234

Date & Time: July 9, 1989, 14:30 Local Registration: N23916

Aircraft: PIPER PA-38-112 Aircraft Damage: Substantial

**Defining Event:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

THE FLIGHT INSTRUCTOR INITIATED A SIMULATED ENGINE FAILURE AT 3500 FEET ABOVE MEAN SEA LEVEL. THE STUDENT PERFORMED THE EMERGENCY PROCEDURES BUT WHEN HE TURNED FINAL HE WAS TOO HIGH TO LAND ON THE RUNWAY. THE FLIGHT INSTRUCTOR TOOK CONTROL OF THE AIRPLANE AND INTENDED TO MAKE ANOTHER 360 DEGREE PRIOR TO LANDING. AS SOON AS THE AIRPLANE ENTERED THE BANK, IT STALLED. THE FLIGHT INSTRUCTOR ATTEMPTED TO RECOVER BY APPLYING FULL POWER BUT THE AIRPLANE DID NOT RETURN TO LEVEL FLIGHT PRIOR TO STRIKING THE GROUND.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FLIGHT INSTRUCTOR'S FAILURE TO TAKE CORRECTIVE ACTION IN SUFFICIENT TIME TO PREVENT THE AIRPLANE FROM STRIKING THE GROUND.

#### **Findings**

Occurrence #1: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

#### **Findings**

1. (F) EMERGENCY PROCEDURE - SIMULATED - PILOT IN COMMAND(CFI)

2. (C) PLANNED APPROACH - POOR - DUAL STUDENT

-----

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### Findings

3. (C) SUPERVISION - INADEQUATE - PILOT IN COMMAND(CFI)
4. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND(CFI)

Page 2 of 6 LAX89LA234

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial	Age:	63,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical–w/ waivers/lim	Last FAA Medical Exam:	February 3, 1989
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	9100 hours (Total, all aircraft), 10 hours (Total, this make and model), 12 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 LAX89LA234

## **Aircraft and Owner/Operator Information**

Aircraft Make:	PIPER	Registration:	N23916
Model/Series:	PA-38-112 PA-38-112	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	38-79A1065
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	June 30, 1989 Annual	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	7 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2048 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-235-L2C
Registered Owner:	MICHAEL J DUNLAP	Rated Power:	110 Horsepower
Operator:	DUNLAP, MICHAEL J	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	25 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots / 8 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	340°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	20°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ition	
Departure Point:	SAN CARLOS , CA (SQL)	Type of Flight Plan Filed:	None
Destination:	HOLLISTER , CA	Type of Clearance:	None
Departure Time:	09:30 Local	Type of Airspace:	Airport advisory area

Page 4 of 6 LAX89LA234

## **Airport Information**

Airport:	FRAZIER LAKE AIRPARK	Runway Surface Type:	Grass/turf
Airport Elevation:	151 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	25	IFR Approach:	None
Runway Length/Width:	2500 ft	VFR Approach/Landing:	Simulated forced landing

## Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	36.889896,-121.240028(est)

Page 5 of 6 LAX89LA234

#### **Administrative Information**

Investigator In Charge (IIC):	Wilcox, Thomas	
Additional Participating Persons:	GEORGE KOBELNYK; ANCHORAGE , AK	
Original Publish Date:	March 29, 1991	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=26443	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX89LA234