



Aviation Investigation Final Report

Location:	GRANADA HILLS, California	Accident Number:	LAX91FA324
Date & Time:	July 22, 1991, 17:00 Local	Registration:	N77CQ
Aircraft:	BEECH 95-C55	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	3 Fatal
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

DURING A VISUAL APPROACH TO THE AIRPORT, THE TOWER CONTROLLER NOTICED THAT THE AIRPLANE WAS HIGH, AND INSTRUCTED THE PILOT TO GO AROUND AND ENTER A RIGHT DOWNWIND. REPEATED INSTRUCTIONS TO TURN TO DOWNWIND BROUGHT NO RESPONSE UNTIL A TURN WAS FINALLY INITIATED. AT THAT TIME THE PILOT DECLARED AN EMERGENCY, REPORTING THAT HE WAS HOLDING FULL BACK ELEVATOR, TRYING TO KEEP THE AIRPLANE IN THE AIR, AND THAT IT LOOKED LIKE HIS ELEVATORS WERE STUCK. THE AIRPLANE CONTINUED AWAY FROM THE AIRPORT AND ENTERED A NEAR VERTICAL HIGH SPEED DESCENT INTO A STORAGE BUILDING. INVESTIGATION REVEALED BOTH ELEVATOR TRIM ACTUATORS AT A 4 DEG NOSE DOWN TRIM POSITION, AND EVIDENCE INDICATES A 40 DEG DOWN ELEVATOR POSITION. NO MALFUNCTION OF THE ENGINES OR FLIGHT CONTROLS WERE FOUND. THE AUTOPILOT SYSTEM CONTROL MODULE WAS DESTROYED. THE PILOT HAD RECEIVED 7 HOURS OF TRAINING IN THE AIRPLANE, AND HAD 20 HOURS TOTAL TIME IN THE AIRPLANE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A LOSS OF DIRECTIONAL CONTROL FOLLOWING AN UNDETERMINED AUTOPILOT FAILURE, DURING WHICH THE PILOT FAILED TO PERFORM THE EMERGENCY PROCEDURE TO CORRECT A MIS-TRIM CONDITION. CONTRIBUTING TO THE ACCIDENT WAS A PERCEIVED ELEVATOR CONTROL PROBLEM; THE INABILITY OF THE PILOT TO OVERPOWER THE MIS-TRIM CONDITION; AND A LACK OF UNDERSTANDING AND TRAINING IN AUTOPILOT SYSTEMS AND FAILURES.

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: GO-AROUND (VFR)

Findings

1. (F) FLT CONTROL SYST,ELEVATOR CONTROL - MOVEMENT RESTRICTED
 2. (C) DIRECTIONAL CONTROL - NOT POSSIBLE - PILOT IN COMMAND
 3. (F) PHYSICAL STRENGTH OVERLOAD - PILOT IN COMMAND
 4. (C) AUTOPILOT/FLIGHT DIRECTOR - UNDETERMINED
 5. (F) AUTOPILOT - NOT UNDERSTOOD - PILOT IN COMMAND
 6. (F) INADEQUATE TRANSITION/UPGRADE TRAINING - CHECK PILOT
 7. (C) TRIM SETTING - NOT CORRECTED - PILOT IN COMMAND
 8. (F) LACK OF FAMILIARITY WITH AIRCRAFT - PILOT IN COMMAND
 9. (C) EMERGENCY PROCEDURE - NOT PERFORMED - PILOT IN COMMAND
 10. (F) INADEQUATE TRAINING(EMERGENCY PROCEDURE(S)) - FLIGHT INSTRUCTOR(ON GROUND)
-

Occurrence #2: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: APPROACH - VFR PATTERN - DOWNWIND

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: DESCENT - UNCONTROLLED

Factual Information

Pilot Information

Certificate:	Private	Age:	50, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim	Last FAA Medical Exam:	February 14, 1990
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	555 hours (Total, all aircraft), 20 hours (Total, this make and model), 20 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N77CQ
Model/Series:	95-C55 95-C55	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	TE-299
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	June 20, 1991 Annual	Certified Max Gross Wt.:	5300 lbs
Time Since Last Inspection:	16 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	3698 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520-C
Registered Owner:	BARGMAN, STUART	Rated Power:	285 Horsepower
Operator:	BARGMAN, STUART	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	VNY ,799 ft msl	Distance from Accident Site:	4 Nautical Miles
Observation Time:	17:05 Local	Direction from Accident Site:	153°
Lowest Cloud Condition:	Scattered / 20000 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	27°C / 16°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	SAN JOSE , CA (SJC)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	VFR
Departure Time:	15:21 Local	Type of Airspace:	Class D

Airport Information

Airport:	VAN NUYS VNY	Runway Surface Type:	Asphalt
Airport Elevation:	799 ft msl	Runway Surface Condition:	Dry
Runway Used:	16R	IFR Approach:	None
Runway Length/Width:	8001 ft / 150 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	2 Fatal	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 Fatal	Latitude, Longitude:	34.289405,-118.500534(est)

Administrative Information

Investigator In Charge (IIC):	Erickson, Scott
Additional Participating Persons:	TOM HENNESSEE; VAN NUYS , CA SCOTT BOYLE; ARVADA , CO MIKE GRIMES; LANCASTER , CA JOHN WARD; WICHITA , KS
Original Publish Date:	July 31, 1992
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=27015

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).