



Aviation Investigation Final Report

Location: BIG LAKE, Alaska Accident Number: ANC95LA155

Date & Time: September 2, 1995, 15:30 Local Registration: N9033L

Aircraft: CHAMPION 7GCBC Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT WAS LANDING ON A LAKE IN A FLOAT EQUIPPED AIRPLANE AND WAS PERFORMING A CURVING APPROACH TO GLASSY WATER. DURING THE LANDING APPROACH, THE AIRPLANE DEVELOPED A HIGH RATE OF DESCENT. JUST BEFORE TOUCHDOWN, THE PILOT ADDED ENGINE POWER, BUT THE AIRPLANE LANDED HARD ON THE WATER. THE AIRPLANE RECEIVED DAMAGE TO THE LEFT FLOAT, LEFT FLOAT STRUT, AND FUSELAGE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN A PROPER RATE OF DESCENT DURING THE APPROACH TO LAND, AND HIS MISJUDGMENT OF ALTITUDE TO FLARE FOR LANDING ON GLASSY WATER. THE GLASSY WATER CONDITION WAS A RELATED FACTOR.

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) TERRAIN CONDITION - WATER, GLASSY

2. (C) PROPER DESCENT RATE - NOT MAINTAINED - PILOT IN COMMAND

3. (C) FLARE - MISJUDGED - PILOT IN COMMAND

Page 2 of 6 ANC95LA155

Factual Information

On September 2, 1995, about 1530 Alaska daylight time, a float equipped Champion 7GCBC, N9033L, crashed during landing on a lake, about 6 miles southwest of Big Lake, Alaska. The airplane was being operated as a visual flight rules (VFR) local area personal flight when the accident occurred. The airplane, owned and operated by the pilot, sustained substantial damage. The certificated commercial pilot, the sole occupant, was not injured. Visual meteorological conditions prevailed. The flight originated at the Lake Hood Seaplane base, Anchorage, Alaska, about 1500.

The pilot reported that he was landing on 7 Mile Lake in a northeasterly direction and was performing a curving approach to glassy water. During the landing approach, the airplane developed a high rate of descent. Just before touchdown, the pilot added engine power but the airplane experienced a hard landing on the water. The airplane received damage to the left float, left float strut, and fuselage.

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	30,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical-no waivers/lim.	Last FAA Medical Exam:	December 1, 1994
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	480 hours (Total, all aircraft), 70 hours (Total, this make and model), 360 hours (Pilot In Command, all aircraft), 80 hours (Last 90 days, all aircraft), 40 hours (Last 30 days, all aircraft)		

Page 3 of 6 ANC95LA155

Aircraft and Owner/Operator Information

Aircraft Make:	CHAMPION	Registration:	N9033L
Model/Series:	7GCBC 7GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	260-70
Landing Gear Type:	Float	Seats:	2
Date/Type of Last Inspection:	September 1, 1995 100 hour	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	4 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1563 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-320-A2B
Registered Owner:	JEFFREY D. ZAJICEK	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ANC,71 ft msl	Distance from Accident Site:	18 Nautical Miles
Observation Time:	18:00 Local	Direction from Accident Site:	160°
Lowest Cloud Condition:	Scattered / 5500 ft AGL	Visibility	90 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	17°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipita	tion	
Departure Point:	ANCHORAGE , AK (LHD)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	Class G

Page 4 of 6 ANC95LA155

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	61.460666,-150.090393(est)

Page 5 of 6 ANC95LA155

Administrative Information

Investigator In Charge (IIC):	Erickson, Scott	
Additional Participating Persons:	WILBUR KEITH; ANCHORAGE , AK	
Original Publish Date:	March 6, 1996	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=2729	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC95LA155