



# **Aviation Investigation Final Report**

Location: ANIAK, Alaska **Accident Number:** ANC95LA171

Date & Time: September 17, 1995, 15:00 Local Registration: N3334M

Aircraft: Substantial PIPER PA-12 Aircraft Damage:

**Defining Event:** Injuries: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported he was landing on a 6,000 foot long gravel runway. He said he did not see a soft, gravel berm on the runway prior to landing. The accident airplane's main landing gear encountered the gravel berm, and the left main wheel separated from the landing gear at the axle. The airplane subsequently nosed down.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's selection of an unsuitable portion of the 6,000 foot long gravel runway for landing. A factor associated with the accident was: the soft gravel berm on the runway.

### **Findings**

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING

#### **Findings**

1. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION - BERM

- 2. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA SELECTED PILOT IN COMMAND
- 3. LANDING GEAR, WHEEL SEPARATION

Occurrence #2: NOSE DOWN Phase of Operation: LANDING

Page 2 of 6 ANC95LA171

### **Factual Information**

On September 17, 1995, about 1500 Alaska daylight time, a wheel equipped Piper PA-12 airplane, N3334M, owned and operated by the pilot, sustained substantial damage while landing at Aniak Airport, Aniak, Alaska. The solo private pilot was not injured. The personal flight operated without a flight plan in visual meteorological conditions. The flight departed Grayling, Alaska, time unknown, and the destination was Aniak.

The pilot reported soon after he landed on the 6,000 foot long gravel runway, the main landing gear encountered an unseen, soft gravel berm. He said the left main landing gear wheel sheared at the axle, and the airplane nosed down.

#### **Pilot Information**

Certificate:	Private	Age:	54,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 30, 1994
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	98 hours (Total, all aircraft), 24 hour	s (Total, this make and model)	

Page 3 of 6 ANC95LA171

## **Aircraft and Owner/Operator Information**

Aircraft Make:	PIPER	Registration:	N3334M
Model/Series:	PA-12 PA-12	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	12-2192
Landing Gear Type:	Tailwheel	Seats:	3
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-235-C
Registered Owner:	CARL A. WALKER	Rated Power:	100 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ANI ,88 ft msl	Distance from Accident Site:	
Observation Time:	15:15 Local	Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Unknown	Visibility	10 miles
Lowest Ceiling:	Overcast / 5000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	16°C / 11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	GRAYLING , AK	Type of Flight Plan Filed:	None
Destination:	(ANI)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class E

Page 4 of 6 ANC95LA171

## **Airport Information**

Airport:	ANIAK ANI	Runway Surface Type:	Gravel
Airport Elevation:	88 ft msl	Runway Surface Condition:	Dry;Soft
Runway Used:	10	IFR Approach:	None
Runway Length/Width:	6000 ft / 150 ft	VFR Approach/Landing:	Full stop;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	61.199489,-158.59909(est)

Page 5 of 6 ANC95LA171

#### **Administrative Information**

Investigator In Charge (IIC):	Labelle, James	
Additional Participating Persons:	GENE D CORDLE; ANCHORAGE , AK	
Original Publish Date:	May 9, 1996	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=2741	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC95LA171