

Aviation Investigation Final Report

Location: COALINGA, California Accident Number: LAX92LA253

Date & Time: June 18, 1992, 18:30 Local Registration: N626NP

Aircraft: PIPER PA-60-700P Aircraft Damage: Substantial

Defining Event: 4 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT ALIGNED THE AIRCRAFT WITH RUNWAY 32 FOR LANDING. HE SAID THAT THERE WAS A 15 KNOT WIND BLOWING FROM 270 DEGREES AND THAT HE ENTERED A LEFT CRAB AS THE AIRCRAFT DESCENDED FOR THE RUNWAY. AS THE AIRCRAFT APPROACHED THE RUNWAY THE PILOT SAID HE ENTERED A SLIP. THE AIRCRAFT LANDED SHORT AND THE LEFT LANDING GEAR COLLIDED WITH THE APPROACH EDGE OF THE RUNWAY. THE PILOT SAID THAT HE HEARD A MUFFLED BANG AND A POP NOISE FOLLOWED BY A LOUD FLOPPING NOISE FROM THE LEFT MAIN LANDING GEAR AS THE AIRCRAFT SKIDDED DOWN THE RUNWAY. AT APPROXIMATELY MIDFIELD THE AIRCRAFT SKIDDED OFF THE LEFT SIDE OF THE RUNWAY AND IMPACTED A WIND DIRECTION INDICATOR. THE INDICATOR WAS LOCATED ABOUT 100 FEET LEFT OF RUNWAY 32. THE NOSE GEAR AND RIGHT MAIN LANDING GEAR COLLAPSED DURING THE AIRCRAFT'S GROUND SLIDE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO ATTAIN THE PROPER TOUCHDOWN POINT AND MISJUDGING THE AIRCRAFT'S DISTANCE FROM THE RUNWAY. CONTRIBUTING TO THIS ACCIDENT WAS THE CROSSWIND CONDITION AND THE NOSE AND MAIN LANDING GEAR COLLAPSING DUE TO OVERLOAD.

Findings

Occurrence #1: UNDERSHOOT

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (C) DISTANCE - MISJUDGED - PILOT IN COMMAND

3. (C) PROPER TOUCHDOWN POINT - NOT ATTAINED - PILOT IN COMMAND

Occurrence #2: GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

4. (F) LANDING GEAR, TIRE - BURST

5. (F) LANDING GEAR, MAIN GEAR - OVERLOAD

6. (F) LANDING GEAR, NOSE GEAR - OVERLOAD

Page 2 of 5 LAX92LA253

Factual Information

Pilot Information

Certificate:	Commercial	Age:	57,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 11, 1991
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	5900 hours (Total, all aircraft), 1300 hours (Total, this make and model), 40 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N626NP
Model/Series:	PA-60-700P PA-60-700P	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	608423014
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	April 20, 1992 Annual	Certified Max Gross Wt.:	6356 lbs
Time Since Last Inspection:	48 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	1226 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	TIO-540-OU2A
Registered Owner:	TRUSTEE, NILS P.	Rated Power:	350 Horsepower
Operator:	TRUSTEE, NILS P.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 LAX92LA253

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	CONCORD , CA (CCR)	Type of Flight Plan Filed:	None
Destination:	(308)	Type of Clearance:	None
Departure Time:	17:45 Local	Type of Airspace:	Class G

Airport Information

Airport:	HARRIS RANCH 308	Runway Surface Type:	Asphalt
Airport Elevation:	470 ft msl	Runway Surface Condition:	Dry
Runway Used:	32	IFR Approach:	None
Runway Length/Width:	2820 ft / 30 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	36.18988,-120.389862(est)

Page 4 of 5 LAX92LA253

Administrative Information

Investigator In Charge (IIC): Wall, James

Additional Participating Persons:

Original Publish Date: September 28, 1993

Last Revision Date:

Investigation Class: Class
Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=27653

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX92LA253